

Detroit
Edison

Donald A. Wells
Manager-Construction Quality Assurance
2000 Second Avenue
Detroit, Michigan 48226
(313) 237-8000

DMB/50.55(e)

58-3f1

August 25, 1981

EF2-54,143



Mr. James G. Keppler, Director
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Keppler:

Subject: Interim Report of 10CFR50.55(e) Item on Transversing In-Core
Probe System (#36)

This additional interim report on the Transversing In-Core Probe System problem has been prepared to provide you with the current status of this problem.

This item was originally reported to Mr. R. Knop of NRC-Region III by Detroit Edison's Mr. H. A. Walker, Supervisor-Construction Quality Assurance on December 29, 1980.

At that time, Engineering investigation indicated that the transversing in-core probe instrument tubing is possibly deficient. This determination was made by Project Design and Field Engineering while doing a design analysis of the thermal movements associated with the primary containment liner during a loss of coolant accident (LOCA).

The Detroit Edison Engineering Research Department mocked up the existing design and performed tests based on the thermal movement associated with a LOCA. These tests have been documented to provide a basis for acceptance/verification of the existing design in a forthcoming report. The analysis contained in the report should resolve this item.

Another report on this item, either interim or final, is scheduled to be sent to you on or before December 23, 1981. If you have questions concerning this matter, please contact Mr. H. A. Walker, Supervisor-Construction Quality Assurance.

Very truly yours,

DAW

IE27
51/9

HAW:ma

8109030195 810825
PDR ADOCK 05000341
S PDR

AUG 27 1981

Mr. James G. Keppler, Director
Page Two

August 25, 1981
EF2-54143

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
Division of Reactor Inspection Programs
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Bruce Little, Resident Inspector
U.S. Nuclear Regulatory Commission
Resident Inspectors Office
6450 North Dixie Highway
Newport, Michigan 48166