

CONTROL BLOCK: 

--	--	--	--	--	--

 (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	A	P	P	S	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5					
LICENSEE CODE								LICENSE NUMBER								LICENSE TYPE								CAT 58							

CON'T

0	1	L	6	0	5	0	-	0	2	9	3	7	0	7	3	0	8	1	8	0	8	2	8	8	1	9					
REPORT SOURCE								DOCKET NUMBER								EVENT DATE								REPORT DATE							

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On July 30, 1981, during a reactor scram, rod #22-11 was observed to have a scram time (9.4 seconds) in excess of the 7 second limit of T.S. 3.3.C.3. A priority "A" MR was issued to investigate and determine cause. After shutdown margin was confirmed by G.E., the rod was withdrawn during power operation and scram tested under seven seconds. A review of past scram times indicates this is an isolated event.

0	9	R	B	11	E	12	B	13	C	R	D	R	V	E	14	Z	15	Z	16	17	8	1	21	0	4	5	24	0	3	28	L	30	0	32	X	18	A	19	Z	20	Z	21	0	0	0	0	37	N	23	N	24	W	25	G	0	8	0	26
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP SUBCODE		VALVE SUBCODE		LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER																

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The most probable cause has been determined to be excessive seal leakage. This rod is presently being constantly monitored and future scram times will be evaluated to determine if additional corrective action is required.

1	0	X	28	0	0	0	29	Scram	30	A	31	Observation	32	1	Z	33	Z	34	NA	35	NA	36	1	0	0	0	37	Z	38	NA	39	1	0	0	0	40	NA	41	1	Z	42	NA	43	2	N	44	8109080201 810828 PDR ADOCK 05000293 S PDR	45	NA	46	68	69	80
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE		PERSONNEL EXPOSURES		PERSONNEL INJURIES		LOSS OF OR DAMAGE TO FACILITY		PUBLICITY		ISSUED DESCRIPTION		NAME OF PREPARER		PHONE		NRC USE ONLY																					

G. G. Whitney

617-746-7900