

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

TELEPHONE: AREA 704
373-4083

August 24, 1981

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Re: McGuire Nuclear Station
Docket No. 50-369



Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report R0-369/81-125. This report concerns T.S. 3.3.1, "As a minimum, the reactor trip system instrumentation channels and interlocks of Table 3.3-1 shall be operable..." This incident was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,


William O. Parker, Jr.

PBN/php
Attachment

cc: Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Bill Lavalee
Nuclear Safety Analysis Center
P. O. Box 10412
Palo Alto, California 94303

Ms. M. J. Graham
Resident Inspector-NRC
McGuire Nuclear Station

IE22
S
1/1