

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N C M G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

REPORT SOURCE L 5 0 5 0 0 0 3 6 9 7 0 8 1 0 8 1 3 0 8 2 4 8 1 3

DOCKET NUMBER 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

3 2 While in Mode 2, Channel 1 of the Engineered Safety Features (ESF) Instrumenta-

3 3 tion for Refueling Water Storage Tank (FWST) level failed due to a faulty trans-

3 4 mitter. The channel was not placed in the tripped condition within 1 hour as re-

3 5 quired by T.S. 3.3.2 which is reportable per T.S.6.9.1.12(f). Since during the

3 6 time of the incident there were no accidents or significant changes in FWST

3 7 level, in addition to availability of trip logic, the health and safety of the

3 8 public were not affected.

3 9

SYSTEM CODE I B 11 CAUSE CODE D 12 CAUSE SUBCODE Z 13 COMPONENT CODE I N S T R U 14 COMP SUBCODE 1 15 VALVE SUBCODE Z 16

LER/NO REPORT NUMBER 17 8 1 SEQUENTIAL REPORT NO. 1 2 6 OCCURRENCE CODE 0 1 REPORT TYPE T REVISION NO. 0

ACTION TAKEN C 18 G 19 SPEED ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 1 0 0 0 ATTACHMENT SUBMITTED Y 22 NPPR FORM SUB N 23 PRIME COMP SUPPLIER L 24 COMPONENT MANUFACTURER B 0 8 0 25

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 Channel 1 of the FWST level was drifting due to a faulty transmitter (Barton,

1 1 Model 386) - exact failure not determined. Personnel on duty at the time of

1 2 failure were unfamiliar with the FW system logic, resulting in their failure to

1 3 trip the channel within 1 hour. The channel was placed in the tripped condition,

1 4 and the transmitter replaced. A method is being developed to prevent recurrence.

1 5

FACILITY STATUS X 26 % POWER 0 0 0 29 OTHER STATUS Mode 2 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Personnel observation 32

ACTIVITY CONTENT Z 33 Z 34 N/A AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36

PERSONNEL EXPOSURES NUMBER 0 37 TYPE Z 38 DESCRIPTION N/A 39

PERSONNEL INJURIES NUMBER 0 40 DESCRIPTION N/A 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43

PUBLICITY ISSUED N 44 DESCRIPTION N/A 45

NAME OF PREPARER Phillip B. Nardoci PHONE: (704) 373-7432

NRC USE ONLY