

50.55(e) DMB  
IE 1845 File copy




KANSAS GAS AND ELECTRIC COMPANY

GLENN L. KOESTER  
VICE PRESIDENT - NUCLEAR

August 28, 1981

Mr. G.L. Madsen, Chief  
Reactor Projects Branch  
U.S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011



KMLNRC 81-108  
Re: Docket No. STN 50-482  
Ref: Interim Report dated June 22, 1981 transmitted  
by GLKoester (KMLNRC 81-090) to GLMadsen, NRC  
Sub: Potential 50.55(e) Report on Nonconforming  
Rockbestos Cable

Dear Mr. Madsen:

This letter is to provide an update on the investigation of the nonconforming Rockbestos cable which was delivered to the Wolf Creek Generating Station site as described in the Referenced Report.

The 130,000 feet of cable has been installed in nonsafety related locations or is on hold in the reel yard. None of the cable has been installed in safety related service. All of the affected cable is identified on Deficiency Reports and will be controlled by these documents pending final engineering disposition. Currently, representative sample specimens are being collected for retesting. When the retest results become available, our Architect/Engineer will issue the final engineering disposition. The results of this investigation and retesting program will be reported to your office on or before November 20, 1981.

If you have any questions regarding this matter, please contact us.

Yours very truly,

*Glenn L. Koester*

GLK:bb  
cc: TVandel  
Resident NRC Inspector

IE 1845  
S/10

8109090337 810828  
PDR ADOCK 05000482  
S PDR