

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

September 1, 1981

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 - DOCKET  
NO. 50-260 - FACILITY OPERATING LICENSE DFR-52 - REPORTABLE OCCURRENCE  
REPORT BFRO-50-260/81043

The enclosed report provides details concerning unit 2 which was made critical from a cold condition with start bus undervoltage relays out of service for the 1A start bus. This report is submitted in accordance with Browns Ferry unit 2 Technical Specification 3.9.A.4.e.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*J. A. Green*  
H. J. Green  
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)

Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Director (40)

Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Bill Lavallee  
Nuclear Safety Analysis Center  
Palo Alto, California 94303

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

*EE27  
5/1*

8109090381 810901  
PDR ADOCK 05000260  
S PDR