

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N C M G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 23 28 LICENSE TYPE 30 37 CAT 38

CON'T

01 1 5 0 5 0 0 0 3 6 9 7 0 8 1 4 8 1 8 0 8 3 1 5 1 9

REPORT SOURCE 50 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 On 8/17/81, it was discovered that during the Zero Power Physics Test Program,

03 the reactor was started up (changed from mode 3 to mode 2) on 8/14 and again on

04 8/16/81 with train "B" of the Control Area Ventilation (VC) System inoperable.

05 This violates TS 3.0.4 which is reportable per TS 6.9.1.12(f). Since the outside

06 air filters on train "B" of VC were functional throughout the incident as veri-

07 fied by subsequent testing, train "B" was actually functional and the health

08 and safety of the public were not affected.

09

10 S I G 11 A 12 A 13 F I L T E R 14 Z 15 Z 16

SYSTEM CODE 9 10 CAUSE CODE 11 12 CAUSE SUBCODE 13 14 COMPONENT CODE 15 16 COMP SUBCODE 17 18 VALVE SUBCODE 19 20

17 18 1 2 7 0 1 T 0

LER/RO REPORT NUMBER 21 22 SEQUENTIAL REPORT NO. 24 25 OCCURRENCE CODE 27 28 REPORT TYPE 29 30 REVISION NO. 31 32

X 18 H 19 Z 20 Z 21 0 0 0 0 Y 22 N 23 L 24 Z 25 9 9 9 9 26

ACTION TAKEN 33 34 FUTURE ACTION 35 36 EFFECT ON PLANT 37 38 SHUTDOWN METHOD 39 40 HOURS 41 42 ATTACHMENT SUBMITTED 43 44 NRC FORM SUB. 45 46 PRIME COMP SUPPLIER 47 48 COMPONENT MANUFACTURER 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The incidents were caused by Operations personnel misinterpreting the Technical

11 Specifications to mean that the inoperable VC train would not prevent a mode

12 change. All Operations personnel will be cautioned to read and interpret Tech-

13 nical Specifications carefully. Personnel will also be encouraged to evaluate

14 decisions independently and not be swayed by the opinions of others.

15

16 X 28 0 0 0 0 29 Mode 2 30 A 31 Personnel observation 32

FACILITY STATUS 33 34 % POW 35 36 OTHER STATUS 37 38 METHOD OF DISCOVERY 39 40 DISCOVERY DESCRIPTION 41 42

17 Z 32 Z 33 N/A 34 N/A 35 N/A 36

ACTIVITY CONTENT 37 38 RELEASED OR RELEASE 39 40 AMOUNT OF ACTIVITY 41 42 LOCATION OF RELEASE 43 44

18 0 0 0 37 Z 38 N/A 39

PERSONNEL EXPOSURES 40 41 NUMBER 42 43 TYPE 44 45 DESCRIPTION 46 47

19 0 0 0 40 N/A 41

PERSONNEL INJURIES 42 43 NUMBER 44 45 DESCRIPTION 46 47

20 0 0 0 42 N/A 43

LOSS OF OR DAMAGE TO FACILITY 44 45 TYPE 46 47 DESCRIPTION 48 49

21 Z 42 N/A 43

PUBLICITY 44 45 DESCRIPTION 46 47

22 N 44 N/A 45

ISSUED 46 47 DESCRIPTION 48 49

NAME OF PREPARER Phillip B. Nardoci PHONE: (704) 373-7432

NRC USE ONLY

810909570