



WTRB/LER

Northern States Power Company

414 Nicollet Mall  
Minneapolis, Minnesota 55401  
Telephone (612) 330-5500

September 1, 1981

Mr J G Keppler  
Office of Inspection & Enforcement  
U S Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137




PRAIRIE ISLAND NUCLEAR GENERATING PLANT  
Docket No. 50-306 License No. DPR-60

Failure of One Unit No. 2 RPI Channel

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.3.2.b since it represents operation with inoperable components as permitted by the Limiting Conditions for Operation.

  
L O Mayer, PE  
Manager of Nuclear Support Services

LOM/DMM/jh

cc: Director, IE, USN (30)  
Director, MIPC, ULNRC (3)  
NRC Resident Inspector  
MPCA  
Attn: J W Ferman

-over-

IE22  
S1/1