

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	2	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5			
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT		58

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	1	6	7	0	7	2	9	8	1	8	0	8	2	7	8	1	9
60	61	DOCKET NUMBER					68	69	EVENT DATE					74	75	REPORT DATE					83			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 DURING ROUTINE TOUR, AN ICE CONDENSER INTERMEDIATE DECK DOOR WAS FOUND FROZEN
0 3 SHUT, CONTRARY TO THE REQUIREMENTS OF T.S. 3.6.5.3. ICE WAS REMOVED FROM THAT
0 4 DOOR AND ONE ADJACENT DOOR AND THE DOORS WERE FREED. THE SOURCE OF THE ICE COULD
0 5 NOT BE LOCATED. ON AUGUST 10, 1981, A DOOR IN THE SAME AREA WAS FOUND FROZEN SHUT.
0 6 THE DOOR WAS FREED THE FOLLOWING DAY. THE REMAINING DOORS WERE OPERABLE. PUBLIC
0 7 HEALTH AND SAFETY WERE NOT AFFECTED. PREVIOUS OCCURRENCES OF FROZEN INTERMEDIATE
0 8 DECK DOORS INCLUDE: RO 81-029/03L-0 AND FOR DOCKET NO. 050-0315; (CONTINUED . . .)

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE					
0	9	S	B	E		B		P	I	P	E	X	X	A	Z				
7	8	9	10	11	12	12	13	13	14	15	16	17	18	19	20				
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.									
17		8	1	—		0	3	0	3	L	—	0							
21	22	23	24	25	26	27	28	29	30	31	32								
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
X	B	Z		Z		0	0	0	0	Y		N		N		W	1	2	0
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)

1 0 THE SOURCE OF WATER WAS DETERMINED TO BE A BROKEN DRAIN LINE FROM AIR HANDLER 4-2B.

1 1 TEMPORARY REPAIRS TO PREVENT FURTHER LEAKAGE WERE COMPLETED AUGUST 14, 1981.

1 2 PERMANENT REPAIRS WILL BE COMPLETED WHEN RADIOLOGICAL CONDITIONS PERMIT.

1 3

1 4

8 9
FACILITY STATUS (28) 1 5 E
2 3 4 5 6 7 8 9
10 11 12 13
% POWER 1 0 0 (29) NA
OTHER STATUS (30)
44
METHOD OF DISCOVERY (31) B
45 46
DISCOVERY DESCRIPTION (32) OPERATOR OBSERVATION
80

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z 33 Z 34 NA NA

7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES

NUMBER		TYPE	DESCRIPTION
1	7	000	(37) Z (38) NA

7 8 9 11 12 13

80

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	NA

1 9		Z 42		LOSS OF OR DAMAGE TO FACILITY TYPE		DESCRIPTION		43	
						NA			

8 9 10
PURITY
ISSUED DESCRIPTION (45)
2 0 N (44)
8109100271 810827
PDR ADDCK 05000316
S PDR
NRC USE ONLY
C9 C9 R9

NAME OF PREPARER DAVID G. WIZNER

PHONE: 616-465-5901, EXT. 1037

SUPPLEMENT TO LER#81-038/03L-0

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES CONTINUED:

80-024/03L-0; 80-021/03L-0; 80-010-03L-0.