

DYMB/LER



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

August 31, 1981



Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DRP-58
Docket No. 50-315

Dear Mr. Keppler:

This is to confirm my telephone report to Mr. E.R. Swanson, NRC Region III Inspector, on August 28, 1981, at approximately 1840 hours at which time I reported that during the preparation of a list of fire doors to be utilized with a plant surveillance procedure for the Donald C. Cook Nuclear Plant a small number of doors thought to be fire rated did not carry the required UL label.

A follow up report will be submitted by September 11, 1981, as required by Technical Specification 6.9.1.8.

Sincerely,

D.V. Shaller

for D.V. Shaller
Plant Manager

/jas

cc: J.E. Dolan
R.S. Hunter
R.W. Jurgensen
R.F. Kroegeer
K.J. Vehstedt
E. Swanson/N. DuBry RO:III
R.C. Callen MPSC
J.M. Hennigan
W. Lavalley EPRI
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (40 copies)
Dir., MIPC (4 copies)

IE22
S/D

SEP 3 1981