

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N C M G S 1 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 27 CAT 28

CONT
0 1 REPORT SOURCE L 5 0 5 0 0 0 3 6 9 7 0 8 0 7 8 1 8 0 9 0 2 8 1 3

DOCKET NUMBER 30 31 EVENT DATE 34 35 REPORT DATE 38 39

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 While in mode 3, it was noticed during routine surveillance that the auxiliary

0 3 feedwater flow gauge at the auxiliary shutdown control panel was indicating a

0 4 flow rate of 50 GPM when no flow was present. It was subsequently declared in-

0 5 operable per T.S. 3.3.3.5 which is reportable pursuant to T.S. 6.9.1.13(b). Be-

0 6 cause of the availability of a redundant instrument located nearby on the auxil-

0 7 iary feedwater turbine driven pump control board, the loss was not considered

0 8 significant and the health and safety of the public were not affected.

0 9

SYSTEM CODE I I D 11 CAUSE CODE A 12 CAUSE SUBCODE C 13 COMPONENT CODE I N S T R U 14 COMP SUBCODE I 15 VALVE SUBCODE Z 16

LER/NO REPORT NUMBER 8 1 EVENT YEAR 1 3 3 SEQUENTIAL REPORT NO. 0 3 OCCURRENCE CODE 0 3 REPORT TYPE L REVISION NO. 0

ACTION TAKEN B 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 ATTACHMENT SUBMITTED N 22 NPROG FORM SUB N 24 PRIME COMP SUPPLIER L 25 COMPONENT MANUFACTURER X 9 9 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 The instrument's mechanical indicator (Hays Republic) was stuck to the indica-

1 1 tor face plate such that freedom of movement was prohibited. (The instrument

1 2 face plate was improperly installed, possibly after calibration or a previous

1 3 maintenance action.) The indicator's face plate was reinstated correctly, and

1 4 the instrument tested and found to be operating properly.

1 5 FACILITY STATUS X 28 % POWER 0 0 0 29 OTHER STATUS Mode 3 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Routine surveillance 32

ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 N/A AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36

PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39

PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43

PUBLICITY ISSUED DESCRIPTION N 44 N/A 45

NRC USE ONLY

NAME OF PREPARER Phillip B. Nardoci PHONE: (704) 373-743