

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 PABVS1200-00000-0034111145

CONT 01 REPORT SOURCE L605000334708038130827819

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 | ESF Instrumentation PS-MS-475A (Bistable for Loop A, Channel III, Low Steam Line  
03 | Pressure) alarmed and reset numerous times and was declared inoperable upon  
04 | verification that steamline pressure was normal. Plant was in Mode I at 100%  
05 | power. There was no effect on the health and safety of the general public  
06 | because the bistable was tripped. Applicable Tech Spec. 3.3.1.1  
07 |  
38 |

09 SYSTEM CODE IB11 CAUSE CODE E12 CAUSE SUBCODE E13 COMPONENT CODE INSTRU14 COMP. SUBCODE Y15 VALVE SUBCODE Z16

17 LER NO. 81 EVENT YEAR 074 SEQUENTIAL REPORT NO. 03 OCCURRENCE CODE L31 REPORT TYPE 032 REVISION NO.

ACTION TAKEN A18 FUTURE ACTION Z19 EFFECT ON PLANT Z20 SHUTDOWN METHOD Z21 HOURS 0000 ATTACHMENT SUBMITTED Y23 NPD-4 FORM SUB. N24 PRIME COMP. SUPPLIER N25 COMPONENT MANUFACTURER W12026

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 | A circuit board capacitor failed damaging an adjacent circuit board. Both  
11 | circuit boards were replaced.  
12 |  
13 |  
14 |

15 FACILITY STATUS E28 % POWER 10029 OTHER STATUS NA30 METHOD OF DISCOVERY A31 DISCOVERY DESCRIPTION Bistable Alarm32

16 ACTIVITY RELEASED OF RELEASE Z33 CONTENT Z34 AMOUNT OF ACTIVITY N/A35 LOCATION OF RELEASE N/A36

17 PERSONNEL EXPOSURES NUMBER 00037 TYPE Z38 DESCRIPTION N/A39

18 PERSONNEL INJURIES NUMBER 00040 DESCRIPTION N/A41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z42 DESCRIPTION N/A43

20 FACILITY DESCRIPTION N/A44

8109110402 810827  
PDR ADCK 05000334  
S PDR

NRC USE ONLY

NAME OF PREPARER W. S. Lacey

PHONE 412-643-6525

Attachment to LER 81-74/C3L  
Beaver Valley Power Station  
Duquesne Light Company  
Docket No. 50-334

No further information is available or needed to satisfy the reporting requirement.