

PACIFIC GAS AND ELECTRIC COMPANY

PG&E

P. O. BOX 7442 • 77 BEALE STREET, 31ST FLOOR, SAN FRANCISCO, CALIFORNIA 94106
TELEPHONE (415) 781-1211

TELECOPIER (415) 543-7813

ROBERT OHLBACH

VICE PRESIDENT AND GENERAL ATTORNEY

CHARLES T. VAN DEUSEN

PHILIP A. CRANE, JR.

HENRY J. LaPLANTE

JOHN B. GIBSON

ARTHUR L. HILLMAN, JR.

CHARLES W. THISSELL

DANIEL E. GIBSON

JACK F. FALLIN, JR.

JOSEPH I. KELLY

ASSISTANT GENERAL COUNSEL

August 27, 1981

GILBERT L. HARRIS
OLYNN WEST, JR.
HOWARD V. GULUS
JAMES C. LOSBON
ROBERT L. BORDON
PETER W. HANSEN
RICHARD F. LUDY
DAVID L. LUDVIGSON
WILLIAM H. EDWARDS
F. RONALD LAURENBERG
ROBERT R. RICKETT
DAVID J. WILLIAMSON
BRUCE R. WORTHINGTONEDWARD J. McMANNEY
DAN GRAYSON LUSBOCK
BENARD J. DELLASANTA
JOSHUA BASLEY
JOSEPH B. ENGLERT, JR.
ROBERT L. HARRIS
DOUGLAS A. ODLESBY
J. PETER BAUMGARTNER
JOHN N. FRYE
J. MICHAEL REIDENBACH
IVOR E. SAMSON
SHIRLEY A. WOOD

SENIOR COUNSEL

DAVID W. ANDERSON
DIANA BERENHAUSEN
LEON S. CASSETT
ALFRED DAIER
DONALD D. EICKSON
PATRICK S. GILSON
PAULA V. HAYNES
RICHARD C. JONES
HARRY W. LONG, JR.
JOHN R. LOW
ROBERT B. MCLENNAN
RICHARD H. MOSE
SHIRLEY A. SANDERSON
JACK W. SHUCK
KENNETH TAYLORPATRICK T. ANNAND
STEVEN P. BURKE
PAMELA CHAPPELLE
GARY P. ENDINAB
DAVID C. GILBERT
STEVEN F. GREENWOLD
JUAN M. JAYE
MERRICK E. LIPSON
JERRICK LORING
AL KRAK MCKENZIE
RICHARD L. MESS
ROBERT A. PETER
JILL ANN SHAFER
LOUIS E. VINCENT

ATTORNEYS

Mr. R. H. Engelken, Director
Office of Inspection and Enforcement
Region V
U. S. Nuclear Regulatory Commission
1990 N. California Boulevard
Walnut Creek Plaza, Suite 202
Walnut Creek, CA 94596

Re: Docket No. 50-275
Docket No. 50-323
Diablo Canyon Units 1 and 2

Dear Mr. Engelken:

On July 28, 1981, we verbally reported a 10 CFR 50.55(e) deficiency concerning the reactor protection and control equipment (Hagen Racks). This letter is the written report required by 10 CFR 50.55(e) and is intended to be the final report concerning the deficiency.

The deficiency involved a modification made to doors on equipment cabinets to allow easy removal for maintenance by replacing the existing hinges with hooks that allow the doors, once they are opened, to be lifted and removed. After the modification was made it was determined that it had the potential to affect the seismic qualification of the enclosed equipment. Accordingly the doors have been returned to their original condition.



RECEIVED

1981 AUG 28 AM 8 57

RECEIVED

IE27
3
1/0

8109110440 810827
PDR ADOCK 05000275
S PDR

Mr. R. H. Engelken

-2-

August 27, 1981

In order to prevent a recurrence, additional instructions have been given to plant personnel concerning requirements for proper authorization of work and the need for an Engineering Department review of any work which might affect seismic qualification of equipment. These requirements are now clearly stated in the Nuclear Plant Administrative Procedure NPAP C-1 "Design Changes".

Very truly yours,

Philip A. Greene, 