

## LICENSEE EVENT REPORT

CONTROL BLOCK:                      (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	C	O	F	S	V	1	2	0	0	-	0	0	0	0	0	0	0	3	4	1	1	2	0	4		5
7	8	9	LICENSEE CODE						14	15	LICENSE NUMBER						25	26	LICENSE TYPE				30	57	CAT		58

0	1	L	6	0	5	0	0	0	2	6	7	7	0	7	1	7	8	1	8	0	8	1	4	8	1	9
7	8	REPORT SOURCE		60	61	DOCKET NUMBER						68	69	EVENT DATE				74	75	REPORT DATE				80		

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On July 17, 1981, and on August 7, 1981, the reactor operated at power with one

0 3 | Class I snubber inoperable. In each instance, the snubber was declared inoperable

0 4 | due to an empty oil reservoir. Degraded mode of LCO 4.3.10. Reportable per Fort St.

0 5 | Vrain Technical Specification AC 7.5.2(b)2. No accompanying occurrence. No affect on

0 6 | public health or safety. Similar occurrences are RO 81-032 and RO 81-040.

0 7 |

0 8 |

0	9	Z	Z	11	E	12	B	13	S	U	P	O	R	T	14	D	15	Z	16													
7	8	SYSTEM CODE		9	10	CAUSE CODE		11	CAUSE SUBCODE		12	COMPONENT CODE			13	COMP. SUBCODE		19	VALVE SUBCODE		20											
LER/RO REPORT NUMBER		EVENT YEAR		21	22	SEQUENTIAL REPORT NO.		23	24	25	OCCURRENCE CODE		26	27	REPORT TYPE		28	29	REVISION NO.		30	31	32									
ACTION TAKEN		FUTURE ACTION		33	34	EFFECT ON PLANT		35	SHUTDOWN METHOD		36	HOURS		37	38	ATTACHMENT SUBMITTED		39	NPRD-4 FORM SUB.		40	PRIME COMP. SUPPLIER		41	42	COMPONENT MANUFACTURER		43	44	45	46	47

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Oil reservoir on BFS-393E empty due to leaking fitting on valve block. Oil reservoir

1 1 | on MSS-149 empty due to leaking piston seal. Fitting tightened and seal replaced. oil

1 2 | reservoir filled, snubbers tested and returned to service. Surveillance interval ad-

1 3 | justed to 62 ± 25%.

1 4 |

1	5	C	28	0	0	4	29	N/A	30	A	31	Personnel Observation	32								
7	8	FACILITY STATUS		9	10	% POWER		11	12	OTHER STATUS		13	METHOD OF DISCOVERY		14	DISCOVERY DESCRIPTION		15	LOCATION OF RELEASE		16
ACTIVITY CONTENT		RELEASED OF RELEASE		17	18	AMOUNT OF ACTIVITY		19	20	PERSONNEL EXPOSURES		21	PERSONNEL INJURIES		22	LOSS OF OR DAMAGE TO FACILITY		23	PUBLICITY		24

1	6	Z	33	Z	34	N/A	35	N/A	36								
7	8	PERSONNEL EXPOSURES		9	10	PERSONNEL INJURIES		11	12	LOSS OF OR DAMAGE TO FACILITY		13	PUBLICITY		14		
NUMBER		TYPE		DESCRIPTION		NUMBER		DESCRIPTION		TYPE		DESCRIPTION		NUMBER		DESCRIPTION	

1	7	0	0	0	37	Z	38	N/A	39								
7	8	PERSONNEL EXPOSURES		9	10	PERSONNEL INJURIES		11	12	LOSS OF OR DAMAGE TO FACILITY		13	PUBLICITY		14		
NUMBER		TYPE		DESCRIPTION		NUMBER		DESCRIPTION		TYPE		DESCRIPTION		NUMBER		DESCRIPTION	

1	8	0	0	0	40	N/A	41	N/A	42								
7	8	PERSONNEL EXPOSURES		9	10	PERSONNEL INJURIES		11	12	LOSS OF OR DAMAGE TO FACILITY		13	PUBLICITY		14		
NUMBER		TYPE		DESCRIPTION		NUMBER		DESCRIPTION		TYPE		DESCRIPTION		NUMBER		DESCRIPTION	

8109150584 810814  
PDR ADDCK 05000267  
S PDR

PHONE: (303) 785-2224