

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONT

0	1
---	---

REPORT SOURCE

1	6	0	5	0	0	0	2	7	2	7	0	9	0	3	8	1	8	0	9	1	4	8	1	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DUCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On September 3, 1981, during a surveillance test, an operator discovered service
03 water leaking from the top secondary coil on No. 11 containment fan coil unit (CFCU),
04 at a rate of approximately 0.5 gallons per minute. In accordance with NRC IE
05 Bulletin 80-24, the NRC was notified of the service water leak in containment by
06 telephone, with written confirmation transmitted within the next 24 hours. No. 11
07 CFCU was declared inoperable and action statement 3.6.2.3.a was entered at 2036 hours,
08 September 3, 1981.

SYSTEM CODE S B 11		CAUSE CODE E 12		CAUSE SUBCODE B 13		COMPONENT CODE H T E X C H 14				COMP SUBCODE G 15		VALVE SUBCODE Z 16					
EVENT YEAR 8 1 21 22		SEQUENTIAL REPORT NO 0 7 8 24 25 26		OCCURRENCE CODE 0 1 28 29		REPORT TYPE T 30		REVISION NO 0 32									
ACTION TAKEN F 33		FUTURE ACTION A 34		EFFECT ON PLANT Z 35		SHUTDOWN METHOD Z 36		HOURS 0 0 0 0 37 38 39 40		ATTACHMENT SUBMITTED Y 41		NPRD-4 FORM SUB Y 42		PRIME COMP. SUPPLIER N 43		COMPONENT MANUFACTURER W 1 2 0 44	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The leakage was due to secondary coil failure. The leaking cooling coil was blank

1 1 flanged off and the CFCU was tested satisfactory and returned to service. Action

1 2 statement 3.6.2.3.a was terminated at 1600 hours, September 4, 1981.

1 3 (81-10, 81-11, 81-31, 81-39, 81-64, 81-72, 81-74, 81-76, 81-77).

1	4																		
7	8	9																	
FACILITY STATUS			% POWER			OTHER STATUS			30	METHOD OF DISCOVERY			DISCOVERY DESCRIPTION						32
1	5	E	28	0	9	6	29	N/A			B	31	Surveillance Test						
7	8	9	10	11	12	13	44			45	46	80							
ACTIVITY CONTENT			RELEASED OF RELEASE			AMOUNT OF ACTIVITY			35				LOCATION OF RELEASE						36
1	6	Z	33	Z	34	N/A			44				N/A						
7	8	9	10	11	12	13	44			45		80							
PERSONNEL EXPOSURES			NUMBER			TYPE			37	DESCRIPTION			39						
1	7	0	0	0	37	Z	38	N/A											
7	8	9	11	12	13	44				80									
PERSONNEL INJURIES			NUMBER			DESCRIPTION			41										
1	8	0	0	0	40	N/A													
7	8	9	11	12	44				80										
LOSS OF OR DAMAGE TO FACILITY			TYPE			DESCRIPTION			43										
1	9	Z	42	N/A															
7	8	9	10	44			80												
PUBLICITY			ISSUED			DESCRIPTION			45	NRG USE ONLY									
2	0	N	44	N/A															
7	8	9	10	44			65			80									

NRC USE ONLY

8109220607 810914
PDR ADOCK 05000272
S PDR

ARER Frank Dickey

PHONE: 609-935-5100