

TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

August 7, 1981

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

OFFICE OF INSPECTION AND ENFORCEMENT BULLETIN 80-08 - RII:JPO 50-259,
-260, -296 - BROWNS FERRY NUCLEAR PLANT - SUPPLEMENT TO FINAL RESPONSE

In response to your letter dated April 7, 1980 which transmitted OIE Bulletin 80-08, we submitted the results of our investigations for the Browns Ferry Nuclear Plant on July 7, 1980. In OIE Inspection Report 50-259, -260, -296/81-13 for the Browns Ferry Nuclear Plant, NRC indicated that TVA committed to provide a supplemental response for OIE Bulletin 80-08. Enclosed is our supplemental response to the final report which constitutes satisfaction of that commitment, identified as Inspector Followup Item (IFI) 50-259, -260, -296/81-13-19.

If you have any questions regarding this subject please call Jim Domer at FTS 857-2584.

To the best of my knowledge, I declare the statements contained herein are complete and true.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

IE11
3
1/1

8109240314 810807
PDR ADOCK 05000259
Q PDR

ENCLOSURE

SUPPLEMENT TO FINAL RESPONSE TO
NRC OIE BULLETIN 80-08
BROWNS FERRY NUCLEAR PLANT

In our July 7, 1980 response to OIE Bulletin 80-08, we stated that backing rings were not used in the manufacturing or installation of the primary piping, containment penetration flued head to outer sleeve welds. This information was based on review of the manufacturers specifications for the penetrations and conversations with TVA employees who were responsible for the installation of the unit 2 penetrations. However, recent recirculation and examination of the radiographs have shown that backing rings were occasionally used to accommodate mismatch during fitup. General Electric Company (GE) installation instructions for erection of primary steam and feedwater piping, specifications 22A21BSAB and 22A2185AA, respectively, permit the use of backing rings to accommodate fitup provided that the designer approves the use of the backing rings. The backing rings were authorized in an as-needed basis for installation. Final acceptance of the containment penetration flued head to outer sleeve welds was based on radiography.

As requested by A. Hirt, NRC OIE Region II, in a telephone call to J. A. Domer on July 23, 1981, we have investigated what NRC considered a breakdown in communications within the TVA organization regarding whether backing rings were utilized. The response from the BFNPP site did not address the subject of backing rings or indicate whether backing rings were utilized or not. The statement that no backing rings were utilized was obtained in a telephone conversation from personnel that had worked on unit 2 penetrations. This was a best-faith effort by us to reconstruct events that occurred years ago during construction. We believe that a breakdown in communication between the BFNPP site and the Chattanooga office did not occur.