

USNRC REGION II
SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE BOX 764

COLUMBIA, SOUTH CAROLINA 29218

T. C. NICHOLS, JR.
VICE PRESIDENT AND GROUP EXECUTIVE
NUCLEAR OPERATIONS

01 AUG 17 10 48:45
August 7, 1981



Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street, N. W.
Atlanta, Georgia 30303

Subject: Virgil C. Summer Nuclear Station
Docket No. 50/395
Defective Valve Parts, IEB-80-21
Nuclear Eng. File - 2.8950

Dear Mr. O'Reilly:

Our previous response on this subject dated February 16, 1981, stated that our review of this problem had indicated that no yokes for active valves were supplied to Virgil C. Summer from Malcolm Foundry. However, as pointed out by an NRC inspector, IEB 80-21 was concerned with valve parts as well as yokes supplied by Malcolm Foundry.

South Carolina Electric and Gas Company (SCE&G) has reviewed this problem again and confirmed that no Malcolm Foundry parts or yokes have been utilized for active valves at Virgil C. Summer Nuclear Station. This is a final report on the subject bulletin. If you require further information, please advise us.

Very truly yours,

T. C. Nichols, Jr.

GDM:TCN:glb

cc: Page Two

IEB
S
1/1

Mr. James P. O'Reilly
August 7, 1981
Page Two

cc: J. C. Szamer
G. H. Fischer
C. C. Nichols, Jr.
I. N. Cyrus
J. Ruoff
O. W. Dixon, Jr.
D. A. Nauman
W. A. Williams, Jr.
R. B. Clary
O. S. Bradham
A. R. Kocn
A. A. Smith
H. Radin
M. N. Browne
H. E. Yocom
B. A. Bursey
J. K. Skolds
J. B. Knotts, Jr.
I&E (Washington)
Document Management Branch
(55e, 21, LER Only)
NPCF
File