

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N C M G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE JO 57 CAT 58

CONT

0 1 REPORT SOURCE L 5 0 5 0 0 d 3 6 9 7 0 8 1 9 8 1 8 0 9 1 8 8 1 9

DOCKET NUMBER 60 61 EVENT DATE 68 69 REPORT DATE 74 75

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 While in Mode 2, both channels of the post-accident containment sump level

0 3 instrumentation indicated water levels when no water was in the sump, and were

0 4 subsequently declared inoperable. This violates T.S.3.3.3.6 which is report-

0 5 able pursuant to T.S.6.9.1.13 (b). Since the transmitters involved provide

0 6 no safety related function and are not necessary for accident mitigation, the

0 7 inoperability of this equipment had no effect on the safe operation of the

0 8 plant or the health and safety of the public.

SYSTEM CODE 1 1 F 11 CAUSE CODE B 12 CAUSE SUBCODE A 13 COMPONENT CODE N S T R U 14 COMP SUBCODE T 15 VALVE SUBCODE Z 16

LER/RO REPORT NUMBER 17 EVENT YEAR 8 1 SEQUENTIAL REPORT NO. 1 4 2 OCCURRENCE CODE 0 3 REPORT TYPE L REVISION NO. 0

ACTION TAKEN E 18 FUTURE ACTION X 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 ATTACHMENT SUBMITTED Y 22 NPRO-4 FORM SUB. N 24 PRIME COMP. SUPPLIER L 25 COMPONENT MANUFACTURER B 0 8 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 The zero level outputs of the containment sump level transmitters (Barton,

1 1 Model 386) had shifted and caused the transmitters to be out of calibration.

1 2 The instruments were functioning in a higher temperature environment than

1 3 installation conditions, causing the fluid filled bellows to expand and con-

1 4 tact the housing walls. The housing walls were bored or machined down to allow

1 5 free movement.

FACILITY STATUS X 28 % POWER 0 0 0 29 OTHER STATUS Mode 2 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Annunciator 32

ACTIVITY CONTENT Z 33 Z 34 N/A AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE N/A 36

PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39

PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43

PUBLICITY ISSUED N 44 DESCRIPTION N/A 45

NRC USE ONLY

NAME OF PREPARER Phillip B. Nardoci

PHONE: (704) 373-7432

8109240607 810918
PDR ADOCK 05000369
S PDR