

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 AR AN 02 00 -0 00 00 -00 04 11 11 11 04 05

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 58

CON'T

01 L 05 00 03 68 08 06 81 09 04 81 09

REPORT SOURCE 60 61 DOCKET NUMBER 62 63 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During a routine engineering inspection, two unsealed penetrations in the

03 wall fire barrier between the cable spreading room and a Motor Control

04 Center (MCC) room were identified to be without a properly maintained

05 fire watch. A fire watch was immediately established as required by

06 T.S.3.7.11. This occurrence is similar to LER 50-368/80-081. Reportable

07 per T.S.6.9.1.9.b.

08

09 AB 11 A 12 C 13 Z Z Z Z Z 14 Z 15 Z 16

SYSTEM CODE 9 10 CAUSE CODE 11 CAUSE SUBCODE 12 COMPONENT CODE 13 COMP SUBCODE 14 VALVE SUBCODE 15

17 81 02 19 03 L 0

LER/RO REPORT NUMBER 17 EVENT YEAR 21 SEQUENTIAL REPORT NO. 24 OCCURRENCE CODE 28 REPORT TYPE 30 REVISION NO. 32

X Z Z Z 00 00 N N Z Z 9 9 9

ACTION TAKEN 33 FUTURE ACTION 34 EFFECT ON PLANT 35 SHUTDOWN METHOD 36 HOURS 37 ATTACHMENT SUBMITTED 41 NPRD-4 FORM SUB 42 PRIME COMP SUPPLIER 43 COMPONENT MANUFACTURER 44

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The fire watch was maintained through the completion of the conduit

11 installation and re-establishment of the permanent fire barrier. Failure

12 was due to inadequate instructions to the contractor personnel. They

13 were cautioned of the importance of maintaining fire barrier integrity

14 and fire watches.

15 E 10 10 NA A Engineering Observation

FACILITY STATUS 28 % POWER 29 OTHER STATUS 30 METHOD OF DISCOVERY 31 DISCOVERY DESCRIPTION 32

16 Z Z NA NA NA

ACTIVITY 33 CONTENT 34 AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36

17 000 Z NA

PERSONNEL EXPOSURES 37 TYPE 38 DESCRIPTION 39

18 000 NA

PERSONNEL INJURIES 40 DESCRIPTION 41

19 Z NA

LOSS OF OR DAMAGE TO FACILITY 42 DESCRIPTION 43

20 N NA

PUBLICITY 44 DESCRIPTION 45

20 N NA

ISSUED 46 DESCRIPTION 47

NRC USE ONLY

NAME OF PREPARER: Chris N. Shively

PHONE: 501/968-2519