


LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6006 • NEW ORLEANS, LOUISIANA 70174 • (504) 386-2345

June 23, 1983

W3I83-0219
Q-3-A35.07.32

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 32
"Stress Analysis for Welded Pipe Support Attachments
Was Not Performed Prior to Fabrication"

REFERENCE: LP&L letter W3I83-0072 dated October 15, 1982

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than June 24, 1983.

At the present time, all corrective action is complete. The piping contractor, Tompkins-Beckwith, is in the process of finalizing SCD No. 32 documentation. LP&L and Ebasco are currently reviewing supporting documentation. This review is expected to be completed by August 12, 1983.

A Final Report will be submitted by August 31, 1983.

Very truly yours,

F. J. Drummond
Project Support Manager - Nuclear

FJD/RWP/MAL:keh

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

3) Mr. E. L. Blake

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

4) Mr. W. M. Stevenson

8307050021 830623
PDR ADOCK 05000382
S PDR

JE-27
1/8