




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

Jul 29, 1983

W3183-0222
Q-3-A35.07.66



Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 66
"Defective G. E. Type AKR Breakers, C-Clips Fall Off"
Third Interim Report

REFERENCE: LP&L letter W3183-0117 dated April 11, 1983

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than June 30, 1983.

At the present time, the material needed for corrected action has been received on site. Corrective action is scheduled to be complete by July 15, 1983.

A Final Report will therefore be submitted by August 5, 1983.

Very truly yours,

F. J. Drummond
Project Support Manager - Nuclear

FJD/RWP/MAL:keh

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

3) Mr. E. L. Blake

4) Mr. W. M. Stevenson