






# SUPPLEMENT TO DVR

DVR NO.				
STA	UNIT.	YEAR	NO.	
D - 12	- 2	- 82	- 96	

PART 1		TITLE OF EVENT		OCCURRED	
		Leak in 2D3 Heater Drain Line		12/24/82	2000
		REASON FOR SUPPLEMENTAL REPORT		DATE	TIME
		Correct report date			
PART 2					
ACCEPTANCE BY STATION REVIEW		 			
DATE		<u>7/29/83</u> <u>7/29/83</u>			
SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION					
		STATION SUPERINTENDENT		8/1/83 DATE	



**Commonwealth Edison**

Dresden Nuclear Power Station

R.R. #1

Morris, Illinois 60450

Telephone 815/942-2920

July 27, 1983

DJS Ltr #83-735

James G. Keppler, Regional Administrator  
Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Updated Reportable Occurrence Report #82-57/03X-1, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(d), abnormal degradation of systems other than those specified in item B.1.e. above designed to contain radioactive material resulting from the fission process. The updated report is supplied to correct a discrepancy in the report date.

D.J. Scott  
Station Superintendent  
Dresden Nuclear Power Station

DJS/kjl

Enclosure

cc: Director of Inspection & Enforcement  
Director of Management Information & Program Control  
U.S. NRC, Document Management Branch  
File/NRC

AUG 02 1983

IE22  
11