



Alabama Power

the southern electric system

June 7, 1983

Director NRR
Nuclear Reactor Regulations
USNRC
Phillips Building
1920 Norfolk Ave.
Bethesda, MD 20014

50-348

Dear Sir;

In accordance with Alabama Power Company Administrative Procedure FNP-O-AP-4, Control of Plant Documents and Records, attached are copies of outstanding Document Control Transmittal sheets.


Please verify that you have these transmittals and the documents referenced on them.

Please sign and return as soon as possible to the following address.

Alabama Power Company
Farley Nuclear Plant
Box 470
Ashford, AL 36312
ATTN: Document Control Supervisor

If you should have any Questions, please call me at (205) 899-5156 Extension (422)

Sincerely,


Joey B. Hudspeth
FNP Document Control Supervisor

JBH:rb

cc: Larry W. Enfinger
File

DESIGNATED ORIGINAL

Certified By Peel E. Reeves

X005

1/1

8308080366 830729
PDR ADOCK 05000348
F PDR

To

Date

NRC Region II Emergency Response Center 5-21-83

Remarks:

Domestic Drawings for Info Only

TRANSMITTED

RETURN REQUESTED

REMARKS

TITLE AND/OR NUMBER

NO.
CPS.

REV.
NO.

COPY
NO.

NO.
CPS.

REV.
NO.

COPY
NO.

See Attached Sheets

See EIP-1160

INSTRUCTIONS TO ADDRESSEE

1. Verify the documents received agree with the above description.
2. Incorporate the transmitted documents into your files.
3. Documents or portions thereof presently in your possession which are superseded by the documents hereby transmitted must be clearly marked "VOID" or "revoked". If return of superseded documents is requested in the above "Return Requested" column, attach the superseded documents to this form prior to returning it.
4. Sign in the space below indicating that you have completed these instructions and return the routing copy of this form to the below address.

WHITE - ROUTING COPY

Alabama Power Company

P. O. Drawer 470

Ashford, Al 36312

YELLOW - SUSPENSE COPY

Attention: Document Control Supervisor

Signature Of Addressee

Remarks:

TRANSMITTED

RETURN REQUESTED

REMARKS

TITLE AND/OR NUMBER

NO. REV
CPS NO.

REV
NO.

COPY NO. 100-100000

NO.
295

REV.
NO.

CGPV
NO

10 - 053 thru 062

FUP-82-1138

1. Verify the documents received agree with the above description.
2. Incorporate the transmitted documents into your files.
3. Documents or portions thereof presently in your possession which are superseded by the documents hereby transmitted, must be clearly marked "COPY" or "TRAYED". If return of superseded documents is requested in the above "Return Requested" column, attach the superseded documents to this form prior to returning it.
4. Sign in the space below indicating that you have completed these instructions and return the routing copy of this form to the below address.

Alabama Power Company

P. Q. Crowder 470

YELLOW - SUSPENSE COPY

Amford, At 36312

Attention: Document Control Supervisor

Signature Of Addressee:

Date

Director NRR (Docket Nos 50-348 & 50-364) 5-9-83

Remarks: Please file the attached with your centralized copy of FNP-O-EIP-8

TRANSMITTED

RETURN REQUESTED

REMARKS

TITLE AND/OR NUMBER

NO.
CPS.

REV.
NO.

COPY
NO.

NO.
CPS.

REV.
NO.

COPY
NO.

FNP-83-0497

10 - 053 thru 062

"On-Call Schedule"

INSTRUCTIONS TO ADDRESSEE

1. Verify the documents received agree with the above description.
2. Incorporate the transmitted documents into your files.
3. Documents or portions thereof presently in your possession which are superseded by the documents hereby transmitted must be clearly marked "VOID" or strayed. If return of superseded documents is requested in the above "Return Requested" column, attach the superseded documents to this form prior to turning it.

Sign in the space below indicating that you have completed these instructions and return the routing copy of this form to the below address.

WHITE - ROUTING COPY

Alabama Power Company

P. O. Drawer 470

YELLOW - SUSPENSE COPY

Asnford, Al 36312

Attention: Document Control Supervisor

Signature Of Addressee

Region II NRC

Date

5-9-83

Remarks: Please file the attached with your controlled copy of FNP-O-EIP-8

TRANSMITTED

RETURN REQUESTED

REMARKS

TITLE AND/OR NUMBER

NO.
CPS.

REV.
NO.

COPY
NO.

NO.
CPS.

REV.
NO.

COPY
NO.

FNP-83-0497

3

- 063

"On-Call Schedule"

064

065

INSTRUCTIONS TO ADDRESSEE

1. Verify the documents received agree with the above description.
 2. Incorporate the transmitted documents into your files.
 3. Documents or portions thereof presently in your possession which are superseded by the documents hereby transmitted must be clearly marked "VOID" or destroyed. If return of superseded documents is requested in the above "Return Requested" column; attach the superseded documents to this form prior to returning it.
- Sign in the space below indicating that you have completed these instructions and return the routing copy of this form to the below address.

WHITE - ROUTING COPY

Alabama Power Company
P. O. Drawer 470

YELLOW - SUSPENSE COPY

Ashford, Al 36312
Attention: Document Control Supervisor

Signature Of Addressee

0450

3-7-83

Remarks:

Region 2 NRC

VOID procedures

INSTRUCTIONS TO ADDRESSEE

- WHITE - ROUTING COPY Alabama Power Company
P. O. Drawer 470
Anniston, Al 36312
- YELLOW - SUSPENSE COPY Attention: Document Control Supervisor

Signature Of Addressee

4867

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO REGION 2 NRC
DATE 830523

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-O-EIP-004	11	36	H6.17
FNP-O-EIP-004	11	37	H6.17
FNP-O-EIP-004	11	35	H6.17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-354)
DATE 830222

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-0-EIP-011	7	38	H6. 17
FNP-0-EIP-011	7	39	H6. 17
FNP-0-EIP-011	7	40	H6. 17
FNP-0-EIP-011	7	41	H6. 17
FNP-0-EIP-011	7	42	H6. 17
FNP-0-EIP-011	7	43	H6. 17
FNP-0-EIP-011	7	44	H6. 17
FNP-0-EIP-011	7	45	H6. 17
FNP-0-EIP-011	7	46	H6. 17
FNP-0-EIP-011	7	47	H6. 17
FNP-0-EIP-008	26	53	H6. 17
FNP-0-EIP-008	26	54	H6. 17
FNP-0-EIP-008	26	55	H6. 17
FNP-0-EIP-008	26	56	H6. 17
FNP-0-EIP-008	26	57	H6. 17
FNP-0-EIP-008	26	58	H6. 17
FNP-0-EIP-008	26	60	H6. 17
FNP-0-EIP-008	26	61	H6. 17
FNP-0-EIP-008	26	62	H6. 17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

4868

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-364)
DATE 830523

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-O-EIP-004	11	38	H6.17
FNP-O-EIP-004	11	39	H6.17
FNP-O-EIP-004	11	40	H6.17
FNP-O-EIP-004	11	41	H6.17
FNP-O-EIP-004	11	42	H6.17
FNP-O-EIP-004	11	43	H6.17
FNP-O-EIP-004	11	44	H6.17
FNP-O-EIP-004	11	45	H6.17
FNP-O-EIP-004	11	46	H6.17
FNP-O-EIP-004	11	47	H6.17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-364)
DATE 830222

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-0-EIP-008	26	59	H6.17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO NRC-1&E WASHINGTON
DATE 821214

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
EP	7	34	H6. 67
EP	7	35	H6. 67
EP	7	36	H6. 67
EP	7	37	H6. 67
EP	7	38	H6. 67
EP	7	39	H6. 67
EP	7	40	H6. 67
EP	7	41	H6. 67
EP	7	42	H6. 67
EP	7	43	H6. 67

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-364)
DATE 830202

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-0-EIP-009	11	41	H6. 17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE

2761

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-364)
DATE 830202

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-O-EIP-009	11	38	H6. 17
FNP-Q-EIP-009	11	39	H6. 17
FNP-O-EIP-009	11	40	H6. 17
FNP-O-EIP-009	11	42	H6. 17
FNP-O-EIP-009	11	43	H6. 17
FNP-O-EIP-009	11	44	H6. 17
FNP-O-EIP-009	11	45	H6. 17
FNP-Q-EIP-009	11	46	H6. 17
FNP-O-EIP-009	11	47	H6. 17
FNP-O-EIP-004	10	38	H6. 17
FNP-O-EIP-004	10	39	H6. 17
FNP-O-EIP-004	10	40	H6. 17
FNP-O-EIP-004	10	41	H6. 17
FNP-Q-EIP-004	10	42	H6. 17
FNP-O-EIP-004	10	43	H6. 17
FNP-O-EIP-004	10	44	H6. 17
FNP-O-EIP-004	10	45	H6. 17
FNP-O-EIP-004	10	46	H6. 17
FNP-O-EIP-004	10	47	H6. 17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

2799

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET 50-348 & 50-364)
DATE 830203

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-0-EIP-015	7	44	H6.17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE _____

2798

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-364)
DATE 830203

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-0-EIP-015	7	38	H6. 17
FNP-0-EIP-015	7	39	H6. 17
FNP-0-EIP-015	7	40	H6. 17
FNP-0-EIP-015	7	41	H6. 17
FNP-0-EIP-015	7	42	H6. 17
FNP-0-EIP-015	7	43	H6. 17
FNP-0-EIP-015	7	45	H6. 17
FNP-0-EIP-015	7	46	H6. 17
FNP-0-EIP-015	7	47	H6. 17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE

2940

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-364)
DATE 830208

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-0-EIP-004	10A	38	H6. 17
FNP-0-EIP-004	10A	39	H6. 17
FNP-0-EIP-004	10A	40	H6. 17
FNP-0-EIP-004	10A	41	H6. 17
FNP-0-EIP-004	10A	42	H6. 17
FNP-0-EIP-004	10A	43	H6. 17
FNP-0-EIP-004	10A	44	H6. 17
FNP-0-EIP-004	10A	45	H6. 17
FNP-0-EIP-004	10A	46	H6. 17
FNP-0-EIP-004	10A	47	H6. 17
FNP-0-EIP-009	11A	38	H6. 17
FNP-0-EIP-009	11A	39	H6. 17
FNP-0-EIP-009	11A	40	H6. 17
FNP-0-EIP-009	11A	42	H6. 17
FNP-0-EIP-009	11A	43	H6. 17
FNP-0-EIP-009	11A	44	H6. 17
FNP-0-EIP-009	11A	45	H6. 17
FNP-0-EIP-009	11A	46	H6. 17
FNP-0-EIP-009	11A	47	H6. 17

INSTRUCTIONS TO THE ADDRESSEE

(1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION

(2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES

(3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED

(4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE

2941

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-364)
DATE 830208

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-0-EIP-009	11A	41	H6.17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE

2941

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-364)
DATE 830208

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-0-EIP-009	11A	41	H6. 17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE

J. M. FARLEY NUCLEAR PLANT
PRODUCTION DEPARTMENT DOCUMENT CONTROL
DOCUMENT TRANSMITTAL FORM
FOR DOCUMENTS TRANSMITTED TO DIRECTOR NRR (DOCKET NOS 50-348 & 50-364)
DATE 830312

DOCUMENT NUMBER	REVISION NUMBER	COPY	DOCUMENT CATEGORY
FNP-0-EIP-008	27	53	H6. 17
FNP-0-EIP-008	27	54	H6. 17
FNP-0-EIP-008	27	55	H6. 17
FNP-0-EIP-008	27	56	H6. 17
FNP-0-EIP-008	27	57	H6. 17
FNP-0-EIP-008	27	58	H6. 17
FNP-0-EIP-008	27	60	H6. 17
FNP-0-EIP-008	27	61	H6. 17
FNP-0-EIP-008	27	62	H6. 17

INSTRUCTIONS TO THE ADDRESSEE

- (1) VERIFY THE DOCUMENTS RECEIVED AGREE WITH THE ABOVE DESCRIPTION
- (2) INCORPORATE THE TRANSMITTED DOCUMENTS INTO YOUR FILES
- (3) DOCUMENTS OR PORTIONS OF DOCUMENTS WHICH ARE SUPERCEDED BY THE ABOVE MUST BE DESTROYED
- (4) SIGN IN THE SPACE BELOW INDICATING THAT YOU COMPLETED THESE INSTRUCTIONS AND RETURN THIS FORM TO THE DOCUMENT CONTROL SUPERVISOR

SIGNATURE OF ADDRESSEE

Revision to Service Building Telephone Directory

INSTRUCTIONS TO ADDRESSEE

1. Verify the documents received agree with the above description.
2. Incorporate the transmitted documents into your files.
3. Documents or portions thereof presently in your possession which are superseded by the documents hereby transmitted must be clearly marked "VOID" or "Revoked." If return of superseded documents is requested in the above "Return Requested" column, attach the superseded documents to this form prior to returning it.
4. Sign in the space below indicating that you have completed these instructions and return the routing copy of this form to the below address.

WHITE - ROUTING COPY
YELLOW - SUSPENSE COPY

Alabama Power Company
P. O. Drawer 470
Ashford, Al 36312
Attention: Document Control Supervisor

Signature Of Addressee