

CD/12

Revision Description This revisionadds a procedure and
a worksheet for estimating
iodine release from
field measurements.QEP
Chapter330-11 Rev. 1
330-S1 Rev. 1
ProcedureJ. Sirovay
Originator

Revision

This procedure is required to be implemented prior to June 9, 1983
because of expiration of Temporary Procedure 1811DRAFT REVIEWFINAL APPROVAL

Tech. Staff Supervisor

Date

Department Head

Date

Originator

Date

Dept. Head

Date

Tech. Staff Supervisor

Date

Asst. Supt.

Date

AUTHORIZATION

Station Superintendent Effective Date

INSTRUCTIONS FOR REVISION INSERTIONREMOVE

QEP 330 - 0 Rev. 15

INSERTQEP 330 - 0 Rev. 16
(New) QEP 330 - 11 Rev. 1
(New) QEP 330 - S1 Rev. 1REVISION RECEIPT FORMPlease sign and date below, and return this sheet to the Officer Supervisor -
Quad Cities Station. Your Station Procedure copy number is 37

Signature

Date

8308090362 830729
PDR ADOCK 05000254
F PDR

-1- (final)

JUN 13 1983

ID/IX

Revision Description This revision

adds a procedure and
a worksheet for estimating
iodine release from
field measurements.

QEP
Chapter330-11 Rev. 1
330-S1 Rev. 1
ProcedureJ. Sirovay
Originator

Revision

This procedure is required to be implemented prior to June 9, 1983because of expiration of Temporary Procedure 1811DRAFT REVIEW

Tech. Staff Supervisor

Date

Department Head

Date

Originator

Date

FINAL APPROVAL

Tech. Staff Supervisor

Date

Tech. Staff Supervisor

Date

Asst. Supt.

Date

AUTHORIZATION

Station Superintendent Effective Date

INSTRUCTIONS FOR REVISION INSERTIONREMOVE

QEP 330-D Rev. 15

INSERT

QEP 330-D Rev. 16
(New) QEP 330-11 Rev. 1
(New) QEP 330-S1 Rev. 1

REVISION RECEIPT FORM

Please sign and date below, and return this page to the Officer Supervisor -
Quad Office Station. Your Station Procedure copy number is 43

Signature

Date