

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	I L D R S 2												0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	3			5									
7	8	LICENSEE CODE												14	LICENSE NUMBER												25	LICENSE TYPE												37	CAT 30	

REPORT SOURCE L 6 0 5 0 0 0 2 3 7 7 1 1 2 3 7 8 8 1 2 1 9 7 8 3

DOCKET NUMBER 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

012 During normal surveillance testing of MSIV closure time, MSIV 2-203-1A closed in
013 5.6 seconds and MSIV 2-203-1C closed in 2.8 seconds after the initiation signal, which
014 did not meet T.S. Table 3.7.D.2 limits of $3 \leq T \leq 5$ sec. Event was of minimal
015 safety significance because other MSIV closure times were within T.S. limits and
016 valves did close. This event has occurred several times before at Dresden, most
017 recently referenced under R.O. #50-249/78-54.

SYSTEM CODE C D 11		CAUSE CODE E 12		CAUSE SUBCODE B 13		COMPONENT CODE V A L V E X 14				COMP. SUBCODE F 15		VALVE SUBCODE D 16	
SERIAL NO. 7 8 9		EVENT YEAR 7 8 21 22		SEQUENTIAL REPORT NO. 0 6 3 24 25 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 0 32			
ACTION TAKEN E 18 34		FUTURE ACTION Z 19 35		EFFECT ON PLANT Z 20 36		SHUTDOWN METHOD Z 21 37		HOURS 0 0 0 0 22 40		ATTACHMENT SUBMITTED N 30 41		PRIME COMP. SUPPLIER N 24 43	
NPRD-4 FORM SUB. N 24 42		COMPONENT MANUFACTURER C 6 6 5 16 44 47											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

MSIV 2-203-1A and 2-203-1C valve timing was out of adjustment. After minor adjustment to speed control valves, MSIV 2-203-1A closed properly in 4.2 sec. Review of historical closing times for MSIV's indicates that minimal time variations occur infrequently because of wear and heat of drywell environment. Valves will be inspected during next refueling outage per DMP 233.

FACILITY STATUS		POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	2	3	4	5	6	7	8	9	10
F	28	0	5	2	29	NA	A	31	Operator Observation
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	2	3	4	5	6	7	8	9	10
Z	32	Z	34	NA		NA			
PERSONNEL EXPOSURES		PERSONNEL INJURIES		LOSS OR OR DAMAGE TO FACILITY		PUBLICITY		NRC USE ONLY	
1	2	3	4	5	6	7	8	9	10
0	0	0	35	Z	36	NA			
0	0	0	37			NA			
0	0	0	38			NA			
0	0	0	39			NA			
0	0	0	40			NA			
0	0	0	41			NA			
0	0	0	42			NA			
0	0	0	43			NA			
0	0	0	44			NA			
0	0	0	45			NA			
0	0	0	46			NA			
0	0	0	47			NA			
0	0	0	48			NA			
0	0	0	49			NA			
0	0	0	50			NA			