



September 7, 1982

Log No. K82-1301  
FILE: RR 2 (NP-33-82-41)

Docket No. 50-346  
License No. NPF-3

Mr. James G. Keppler  
Regional Administrator, Region III  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence 82-036  
Davis-Besse Nuclear Power Station Unit 1  
Date of Occurrence: August 8, 1982

Enclosed are three copies of Licensee Event Report 82-036 with a supplemental information sheet, which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray  
Station Superintendent  
Davis-Besse Nuclear Power Station

TDM/lmr  
Enclosure

cc: Mr. Richard DeYoung, Director  
Office of Inspection and Enforcement  
Encl: 30 copies

Mr. Norman Haller, Director  
Office of Management and Program Analysis  
Encl: 3 copies

Mr. Walt Rogers  
NRC Resident Inspector  
Encl: 1 copy

8209160206 820907  
PDR ADOCK 05000346  
S PDR

SEP 10 1982

LC 22