

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	J	S	G	S	2	(2)	o	o	-	0	0	0	0	0	-	0	0	(3)	4	1	1	1	1	(4)			(5)	
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58

CON'T

0 1
7 8

REPORT SOURCE 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DOCKET NUMBER 61 62 63 64 65 66 67 68

EVENT DATE 69 70 71 72 73 74

REPORT DATE 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 At 1515 hours, August 6, 1982, during routine operation, the Control Room Operator

received indication of malfunction of the Containment Gas Monitor System, Channel 2R12A.

041 The monitor was declared inoperable and Action Statement 3.3.3.1b Actions 24 and 25

5 6 were entered at 1515 hours.

06 | _____

07 _____

08

7 8

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

C I 11 E 12 B 13 I N S T R U 14 S 15 Z 16

9 10 11 12 13 14 15 16

(17) LER/RO REPORT NUMBER 8 2 —

EVENT YEAR —

SEQUENTIAL REPORT NO. 0 7 6 /

OCCURRENCE CODE 0 3

REPORT TYPE L —

REVISION NO. 0

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER				
A	18	Z	19	Z	20	Z	21	0	0	0	0	22	Y	23	N	24	A	25	V	1	1	5

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause was a failed test jack, which caused improper electrical connection of the

1 1 | detector and meter. The test jack was replaced and a channel calibration was satis-

1 2 factorily performed. The Containment Gas Radiation Monitor was declared operable and

13 | Action Statement 3.3.1b Actions 24 and 25 were terminated at 2215 hours.

1	4	
---	---	--

FACILITY STATUS						% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
1	5	E	(28)	0	8	2	(29)	NA	B (31) Routine Inspection

ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
1	6	Z	(33)	Z	(34)	NA	NA

PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION	
1	7	0	0	0	(37)	2	(38) NA

[illegible]

7		8		9		11		12		80		
LOSS OF OR DAMAGE TO FACILITY (43)												
TYPE		DESCRIPTION										
1	9	2	(42)	NA								

7 8 9 10
PUBLICITY
ISSUED DESCRIPTION (45)
2 0 N (44) NA
8209160252 820825
PDR ADOCK 05000311
PDR
NRC USE ONLY

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

NAME OF PREPARER

R. Heller

PHONE: (609) 541-5900 629

NRC USE ONLY