

No. 3-82-14/3L

This LER deals with the failure of drywell temperature indication per Tech Spec 3.2.F.

LICENSEE EVENT REPORT

8209160516 820910
PDR ADOCK 0500027B
S PDR

PHONE

215⁶⁸-841-5020⁶⁹