



**LOUISIANA**  
POWER & LIGHT


142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

August 31, 1982

L. V. MAURIN  
Vice President  
Nuclear Operations

W3I82-0022  
Q3-A35.07.52

Mr. John T. Collins, Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



Subject: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency Report No. 52  
"Bi-Metallic Penetration Welds, No Stress Relief"

Reference: 1) LP&L Letter W3K-82-0275

Dear Mr. Collins:

At the present time, the corrective action as described in LP&L letter W3K-82-0275 has not been completed by Associate Piping and Engineering.

A final report will therefore be submitted on November 5, 1982.

Very truly yours,

L. V. Maurin  
Vice-President

- cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555
- 2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

IE 27

8209160583 820831  
PDR ADOCK 05000382  
S PDR