

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 1 1 A 0 A C 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 58 59

CONT

01 REPORT SOURCE L 6 0 1 5 10 10 0 3 3 1 7 0 8 10 9 8 2 3 0 9 0 8 8 2 9
7 8 9 DOCKET NUMBER 58 59 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operation surveillance testing, Reactor Core Isolation Cooling (RCIC) steam line high pressure differential indicating switch PDIS-2442 tripped out-of-spec at 98 inches of water. Technical Specification Table 3.2-B requires the setpoint to be 110 +/- 5 inches of water. Redundant switch PDIS-2441 was operable. There have been seven previous similar occurrences. (See R0 77-52, 77-93, 79-30, 81-23, 82-02, 82-24, and 82-35)

09 SYSTEM CODE C E 11 CAUSE CODE E 12 CAUSE SUBCODE E 13 COMPONENT CODE I N S T R U 14 COMP SUBCODE S 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20
17 LER/RO REPORT NUMBER 8 2 21 22 SEQUENTIAL REPORT NO. 0 5 1 24 25 OCCURRENCE CODE 0 3 28 29 REPORT TYPE L 30 31 REVISION NO. 0 32
ACTION TAKEN E 18 FUTURE ACTION F 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 37 40 ATTACHMENT SUBMITTED N 23 NPRO-4 FORM SUB N 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER B 0 8 0 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Instrument drift. The switch was promptly recalibrated, tested and found satisfactory. PDIS-2442 is a Barton model 288A pressure differential switch. A design change is in progress to replace PDIS-2442 and PDIS 2441 with similar switches with a smaller range to reduce drift problems. The new switches will be installed within 60 days of their receipt.

15 FACILITY STATUS E 28 % POWER 0 7 9 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Surveillance Test 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

16 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 NA 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

14 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

13 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43 8209160593 820908 PDR ADOCK 05000331 S PDR
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

20 PUBLICITY ISSUED DESCRIPTION NA 45 NRC USE ONLY
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER Kimuel L. Hill

PHONE: 319-851-5611