



LONG ISLAND LIGHTING COMPANY

SHOREHAM NUCLEAR POWER STATION

P.O. BOX 818, NORTH COUNTRY ROAD • WADING RIVER, N.Y. 11792

September 16, 1982

SNRC-770

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

SER Issue I.C.8 - Emergency Procedures
Shoreham Nuclear Power Station - Unit 1
Docket No. 50-322

Dear Mr. Denton:

As stated in SNRC-738, the Shoreham Emergency Procedures developed from the BWR Owners' Group Emergency Procedure Guidelines (EPG's) have been reviewed by the vendor (General Electric), and their comments have been incorporated, as appropriate, into these procedures. In addition, Shoreham plant specific data and graphs have also been incorporated.

These revised procedures have been approved by Shoreham's Review of Operations Committee, and fifteen (15) copies are hereby being transmitted for your information and use. A listing of the procedures is included as Attachment 1.

It should be noted that staff comments resulting from the simulator verification of these procedures had previously been incorporated and submitted via SNRC-638 dated 11/23/81.

In view of the above, it is LILCO's understanding that the submittal of these emergency procedures fulfills LILCO's commitment with regard to SER Issue I.C.8, which can now be completely closed on the Shoreham docket.

Should you have any questions, please contact this office.

Very truly yours,

J. L. Smith
Manager, Special Projects
Shoreham Nuclear Power Station

RWG:mp

cc: J. Higgins
All parties

8209200247 820916
PDR ADOCK 05000322
E PDR

~~1300~~
1300 1/15 Etk's
Rec'd

List of Enclosures

Shoreham Nuclear Power Station - Unit 1
Emergency Procedures
From BWROG Guidelines

<u>Title</u>	<u>SP Number</u>	<u>Revision</u>
Level Control Emergency Procedure	29.023.01	1
Cooldown Emergency Procedure	29.023.02	1
Containment Control Emergency Procedure	29.023.03	2
Level Restoration Emergency Procedure	29.923.04	1
Rapid RPV Depressurization Emergency Procedure	29.023.05	1
Reactor Pressure Vessel Flooding Emergency Procedure	29.023.09	2
Transient with Failure to Scram Emergency Procedure	29.024.01	0