

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A	L	J	M	F	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5			
7	8	LICENCE CODE						14	15	LICENSE NUMBER										25	LICENSE TYPE					30	CAT				58

CONT

REPORT SOURCE: 01 L 6 0 5 0 0 0 3 4 8 7 0 8 2 3 8 2 E 0 9 2 1 8 2 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

012 | At 0545 on 8-23-82, the "B" train control room emergency air cleanup
013 | system was declared inoperable due to the failure of the 1B control
014 | room air conditioner fan. Tech. Spec. 3.7.7 requires the "B" train
015 | control room air cleanup system to be operable. Tech. Spec. 3.7.7
016 | action statement requirements were met. The health/safety of the
017 | public was not affected. (This LER is applicable to both Units 1
018 | and 2 of FNP.)

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE	
7	8	S	G	E	B	X	X	X	X	X	X	Z	Z		
		9	10	11	12	13	14	15	16			17	18		
17		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
LER RO REPORT NUMBER		8	2	051		03		L		0					
21		22	23		24	25	26	27	28	29	30	31	32		
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS				ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER				
A	Z	Z	Z	0	0	0	0	N	N	Z	Z999				
33	34	35	36	37	38	39	40	41	42	43	44 45 46 47				

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | This incident was caused by the failure of the fan drive belts. The

1 1 | belts were replaced and the system was returned to service at 1330 on

1 2 | 8-23-82.

1 3 |

1 4 |

7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60	
FACILITY STATUS		1		5		E		28		1		0		0		29		OTHER STATUS		30		METHOD OF DISCOVERY		A		31		DISCOVERY DESCRIPTION		32		Operator Observation		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60																			

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

NA

NA

PERSONNEL EXPOSURES									
NUMBER			TYPE		DESCRIPTION (39)				
1	7	0	0	0	3	Z	38	NA	

PERSONNEL INJURED		DESCRIPTION		
NUMBER				
1	0	0	0	NA

7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100													
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80		81		82		83		84		85		86		87		88		89		90		91		92		93		94		95		96		97		98		99		100	

7	6	5	4	3	2	1	0	NA	80
PUBLICATION ISSUED (4b) DESCRIPTION (4b)								8209300053 820921 PDR AD0CK 05000348	NRC USE ONLY

2 6 N 44 S PDR 68 59 80

NAME OF PREPARER W. G. Hairston, III

PHONE (205) 899-5156