



# MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

September 22, 1982

JAMES P. McGAUGHY, JR.  
ASSISTANT VICE PRESIDENT

Office of Inspection & Enforcement  
U.S. Nuclear Regulatory Commission  
Region II  
101 Marietta St., N.W., Suite 3100  
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station  
Unit 1  
Docket No. 50-416  
License No. NPF-13  
File 0260/L-835.0  
Incorrect Setpoints for RHR  
Injection Valve Differential  
Pressure Switches  
Reference: LER 82-059/01 T-0  
AECM-82/418

On September 9, 1982, during routine leakage tests, it was discovered that the differential pressure switches for the RHR injection valves were found to be incorrectly set. Attached is LER 82-059/01 T-0 with supplementary information.

Yours truly,

*J.P. McGaughy, Jr.*  
For J.P. McGaughy, Jr.

JPM:lm  
Attachment

cc: Mr. N. L. Stampley (w/a)  
Mr. R. B. McGehee (w/o)  
Mr. T. B. Conner (w/o)  
Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)  
Office of Inspection & Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Document Control Desk (w/a)  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8209300072 820922  
PDR ADOCK 05000416  
S PDR

AE1N6

Member Middle South Utilities System

OFFICIAL COPY

LE 27