

DUKE POWER COMPANY

P.O. BOX 33188
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

September 16, 1982

TELEPHONE
(704) 373-4531

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: Oconee Nuclear Station
Docket No. 50-269

Dear Mr. O'Reilly:

On September 3, 1982 your office was informed that several Reactor Building penetrations may not have been leak rate tested per Technical Specification 4.4.1.2.1. Reportable Occurrence Report RO-269/82-14 providing details of this incident was to have been submitted to you by September 16, 1982, pursuant to Technical Specification 6.6.2.1.a(2). However, the investigation of this incident and the preparation of a report are incomplete at this time. It is expected that the investigation and report will be completed, reviewed, and submitted to you no later than September 30, 1982.

Very truly yours,

H.B. Tucker/AV

Hal B. Tucker

JCP/php

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. W. T. Orders
NRC Resident Inspector
Oconee Nuclear Station

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. Philip C. Wagner
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

82 SEP 24 AM 10:07
CENTRO REGION
ATLANTA, GEORGIA

OFFICIAL COPY

8209300130 820916
PDR ADOCK 05000269
S PDR

IE 22