

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

September 24, 1982

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE
REPORT BFRO-50-259/82071

The enclosed report provides details concerning high-pressure coolant
injection condensate header low-level switches failing to operate.
This report is submitted in accordance with Browns Ferry unit 1 Technical
Specification 6.7.2.a(5).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Green
W. J. Green
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

NRC Inspector, Browns Ferry

82 SEP 27 AID

NSNRO REGION II
ATLANTA, GEORGIA

OFFICIAL COPY
IE 22

8209300170 820924
PDR ADOCK 05000259
S PDR