

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

September 27, 1982

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

02 SEP 27 AID: 10
REGION II
ATLANTA, GEORGIA

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE
REPORT BFRO-50-259/82020 - REVISION 2

The enclosed report is a supplement to my letters to you dated April 14,
1982 and July 22, 1982 concerning high unidentified drywell leakage because
of a cracked test connection pipe on the reactor water cleanup system.
This report is submitted in accordance with Browns Ferry unit 1 Technical
Specification 6.7.2.b(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Loper
J. J. Green
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

NRC Inspector, Browns Ferry

8209300287 820927
PDR ADOCK 05000259
S PDR

An Equal Opportunity Employer

OFFICIAL COPY

IE 22