

**LICENSEE EVENT REPORT**

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 14 15 25 26 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

0 1 C A S O S 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT GR

CON'T

REPORT SOURCE L 6 0 5 0 0 0 3 6 1 7 0 8 5 1 8 2 8 0 9 3 0 8 2 9

DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While in Mode 2 motor driven AFW pump 2P-504 was declared inoperable. LCO 3.7.1.2

03 | Action a was entered. There was no consequence to public health and safety since

any one of the remaining two operable AFW pumps would have performed its intended decay

05 heat removal function, if called upon to do so.

0	6	
---	---	--

07 \_\_\_\_\_

08 \_\_\_\_\_

0 9 7 8

SYSTEM CODE

H H 11

9 10

CAUSE CODE

E 12

11

CAUSE SUBCODE

B 13

12

COMP. SUBCODE

P U M P X X 14

13 14

VALVE SUBCODE

B 15

15

Z 16

16

17 LER/RO REPORT NUMBER 8 2 —

SEQUENTIAL REPORT NO. 1 0 5 /

OCCURRENCE CODE 0 3

REPORT TYPE L —

REVISION NO. 0

ACTION TAKEN 33 [B] 34 (18) FUTURE ACTION 35 [Z] 36 (20) EFFECT ON PLANT 37 [Z] 38 (21) SHUTDOWN METHOD 39 [0] 40 [0] 41 [0] 42 [0] HOURS 43 (22) ATTACHMENT SUBMITTED 44 [N] 45 (23) NRPD-4 FORM SUB. 46 [N] 47 (24) PRIME COMP. SUPPLIER 48 [A] 49 (25) COMPONENT MANUFACTURER 50 [B] 51 [5] 52 [8] 53 [0]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The cause for the failure was due to a leaky threaded plug on the pump discharge

casing. Corrective action included cleaning the threads, applying graffoil and

1 2 reinstalling the plug. No additional corrective actions are planned.

13

14

1 5 B 28 0 0 0 29 NA 30 METHOD OF DISCOVERY B 31 Operator Observation 32 DISCOVERY DESCRIPTION 80

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
000	37 Z	NA

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
0	0	0	40
			NA

TYPE		DESCRIPTION		(43)	
1	9	Z	(42)	NA	8210130508 820930 PDR ADOCK 05000361 S PDR

PUBLICITY  
 ISSUED DESCRIPTION (45)  
 2 0 N (44) NA  
 NRC USE ONLY

NAME OF PREPARER

M. B. Ray

PHONE: 714/492-7700