



LOUISIANA
POWER & LIGHT


142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

October 1, 1982

L. V. MAURIN
Vice President
Nuclear Operations

W3I82-0058
Q-3-A35.07.33

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency Report No. 33
"Chilled Water Piping Supports"
Fourth Interim Report

REFERENCES: 1) LP&L Letter W3K-81-0293 dated August 17, 1981
2) LP&L Letter W3K-82-0466 dated July 30, 1982

Dear Mr. Collins:

The corrective action as described in Reference 1 has not yet been completed.
A final report will, therefore, not be submitted until March 11, 1983.

Very truly yours,

L. V. Maurin
L. V. Maurin

LVM/MAL:keh

cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE 27

8210130551 821001
PDR ADOCK 05000382
S PDR