



**LOUISIANA  
POWER & LIGHT**


142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 386-2345

September 30, 1982

L. V. MAURIN  
Vice President  
Nuclear Operations

W3I82-0052  
Q-3-A35.07.48

Mr. John T. Collins, Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



SUBJECT: Waterford SES Unit No. 2  
Docket No. 50-382  
Significant Construction Deficiency Report No. 48  
"Design Application of Break Flanges at Elevated Temperatures"  
Second Interim Report

REFERENCE: LP&L Letter W3K-82-0175 dated March 26, 1982

Dear Mr. Collins:

The corrective action as described in the reference above has not yet been completed. A final report will, therefore, not be submitted until January 17, 1983.

Very truly yours,

L. V. Maurin

LVM/MAL:keh

- cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555
- 2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

IE 27

8210130564 820930  
PDR ADOCK 05000382  
S PDR