

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	J	S	G	S	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5			
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58		59

CON'T

0 1
7 8

REPORT SOURCE 6 0 5 0 0 0 3 1 1 7 0 8 1 4 8 2 8 0 8 1 8 8 2 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 On August 14, 1982, a 1 GPM service water leak was discovered on No. 22 Containment Fan Coil Unit (CFCU). No. 25 CFCU was inoperable at the time, and Action Statement 3.6.2.3.a was in effect. With an additional CFCU inoperable, Action Statement 3.6.2.3.b was entered. The unit was immediately isolated. No. 25 CFCU was repaired later that day, and Action Statement 3.6.2.3.b was terminated. (see LER 82-074) On August 15, a similar leak was discovered on No. 24 CFCU; this unit is in the same group as No. 22, hence, Action Statement 3.6.2.3.a still applied. The events constituted degradation of containment in accordance with Technical Specification 6.9.1.8.c.

SYSTEM CODE		CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE				COMP. SUBCODE	VALVE SUBCODE
S	B	B	A	H	T	E	X	C	Z
9	10	11	12	13	14	15	16	17	18
LER/O REPORT NUMBER		EVENT YEAR	SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE	REVISION NO.		
17	8	2	0	7	5	0	1	T	0
21	22	23	24	25	26	27	28	29	30
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS		ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
D	F	Z	Z	0	0	Y	Y	A	W
33	34	35	36	37	38	39	40	41	42
				0	0	0	0		1
									2
									0
									0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | No. 22 CFCU was repaired by blanking the flanges in the service water piping to the
1 1 | coil. The leak on No. 24 CFCU was repaired with Belzona metal filler. With both
1 2 | units operable, Action Statement 3.6.2.3.a was terminated. New design coils will be
1 3 | installed during the next refueling.
1 4 | (82-074, 82-073, 82-070, 82-040, 82-028)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (1) E (28) % POWER (0) (8) (2) (29) OTHER STATUS (30) NA METHOD OF DISCOVERY (B) (31) ROUTINE INSPECTION DISCOVERY DESCRIPTION (32) Routine Inspection

ACTIVITY CONTENT RELEASED OF RELEASE (1) (6) (Z) (33) (Z) (34) NA AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES		NUMBER		TYPE	DESCRIPTION
1	7	0	0	0	NA

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	0000	40 NA

11 12		LOSS OF OR DAMAGE TO FACILITY		(43)
TYPE		DESCRIPTION		
1	9	Z	(42) NA	

10
PUBLCITY
ISSUED DESCRIPTION (45)
2 0 N (44) NA
PDR ADOCK 05000311
PDR
NRC USE ONLY

NAME OF PREPARER

R. Frahm

PHONE:

609/935-6000 Ext 3078

NRC USE ONLY

017-920