

LICENSEE EVENT REPORT

036720

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 M D C C N 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
 3 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38

1 REPORT SOURCE L 5 0 5 0 0 0 3 1 7 7 0 3 1 7 8 1 3 0 4 1 6 8 1 3
 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 82

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 During the acceptance test of the Unit 1 cable spreading room halon
 3 system, the ventilation exhaust damper in the cable spreading room did
 4 not shut. The damper circuit was rewired and returned to service on
 5 March 27, 1981. The improper damper operation did not affect the
 6 operability of safety systems controlled by tech specs. This is not
 7 a repetitive occurrence.

8 9

9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE
 A A 11 B 12 C 13 Z Z Z Z Z Z 14 Z 15 Z 16
 9 10 11 12 13 14 15 16
 17 LER NO REPORT NUMBER 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER
 F 18 Z 19 Z 20 Z 21 0 0 0 0 22 N 23 N 24 A 25 B 1 13 10 47
 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

0 During construction, the control circuit for Unit 1 cable spreading
 1 room was connected to Unit 2 exhaust damper. Indication for Unit 1
 2 and 2 were also reversed thereby obfuscating the control circuit error.
 3 The control and indication circuits were reworked and the entire cable
 4 spreading room ventilation system checked.

5 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
 E 28 1 0 0 29 NA C 31 Op. Check of New System
 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
 Z 33 Z 34 NA NA
 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
 0 0 0 37 Z 38 NA
 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

8 PERSONNEL INJURIES NUMBER DESCRIPTION (41)
 0 0 0 40 NA
 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)
 Z 42 NA
 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

0 PUBLICITY #ISSUED DESCRIPTION (45)
 N 44 NA
 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

NAME OF PREPARED R. P. Heibel

PHONE (301) 269-4747