

APPROVED BY OMB
3150-0011
EXPIRES 4-30-82

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	S		C		V		C		S		1		2	0		0		-		0		0		0		0		-		0		0		3	4		1		0		0		0		4					5
7	8	LICENSEE CODE										14	LICENSEE NUMBER														25	LICENSEE TYPE										30	CAT										38		

CON'T

0 1 REPORT SOURCE L 6 0 5 0 0 0 3 9 5 7 0 9 2 9 8 2 8 1 0 2 6 8 2 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While going through initial plant startup and having recently entered Mode 4,
0 3 | Technical Specification 4.7.5 requires Service Water Pond level verification
0 4 | at least once every 24 hours. These readings were omitted from 9/22/82 to
0 5 | 9/29/82. There were no adverse consequences since the plant had no inventory
0 6 | of decay heat. Also, it was verified that the pond had not dropped below the
0 7 | Technical Specification minimum level.

[illegible]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The Operator Logs were recently revised. In the revision process, the Service
1 1 Water Pond level entry was omitted by personnel error. The Logs were revised
1 2 to include this surveillance. Also, the Logs were reviewed to ensure that all
1 3 required Tech. Spec. surveillances assigned to be covered on logs were intact
1 4 included. No additional problems were discovered.

FACILITY STATUS (1) 5 (2) B (28) 0 0 0 (29) N/A (30) METHOD OF DISCOVERY (31) NRC Resident Inspector (32) DISCOVERY DESCRIPTION
 ACTIVITY CONTENT RELEASED OF RELEASE (33) Z (34) Z (35) N/A (36) LOCATION OF RELEASE
 (1) 6 (2) Z (33) Z (34) Z (35) N/A (36) N/A

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION
1	7	0	0	0
37	38	Z	N/A	

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
18	000	40	N/A

8 9 11 12
LOSS OF OR DAMAGE TO FACILITY
TYPE DESCRIPTION (43)
1 9 Z (42) N/A
8211040105 821026
PDR ADCK 05000395
PDR

PUBLICATION ISSUED		DESCRIPTION	(45)	NRC USE ONLY									
2	0	N	(44)	N/A									

NAME OF PREPARER Curtis Fields

PHONE: (803) 345-5209