

LICENSEE EVENT REPORT

Attachment to AECM-82/511

Page 1 of 1

CONTROL BLOCK:

							(1)
--	--	--	--	--	--	--	-----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	S	G	G	S	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	LICENSEE CODE						14	LICENSE NUMBER										25	LICENSE TYPE					30	CAT		58	

CON'T

0 1 7 8

REPORT SOURCE L 6 0 5 0 0 0 4 1 6 7 0 9 2 9 8 2 8 1 0 2 8 8 2 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During Non-Nuclear Heatup, Routine Surveillance Procedure 06-OP-1T42-Q-0001 revealed

0 3 | the Fuel Handling Area Vent Supply Isolation Damper (Q1T42F0012) failed to cycle

0 4 | closed in less than 5 seconds (T.S.3.6.6.2). This had no effect on the health or

0 5 | safety of the public and did not constitute a threat to plant safety. This event

0 6 | is being reported pursuant to T.S.6.9.1.13.b. The redundant Fuel Handling Area Vent

0 7 | Supply Isolation Damper (Q1T42F0011) in this line was operable.

0 8 |

7 8 9 80

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE			
7	8	S	D	E	B	V	A	L	V	E	X	B	D				
17		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
17	18	8	2	0	9	3	0	3	L	0							
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
A	Z	Z	Z	Z	0	0	0	0	N	N	A	P	3	4	0		
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Upon investigation, it was found that the cup seal for this isolation damper (Henry
1 1 Pratt, size 8" air operated butterfly valve, 150 lb) was stretched oversize. The
1 2 cup seal was repaired, reinstalled, and the above Surveillance Test satisfactorily
1 3 completed on October 13, 1982. The Action Statements of T.S.3.6.6.2 were satisfied.
1 4 This is a final report.

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
1	5	G	28	0	0	0	29	NA	30	B	31	Surveillance Test		
ACTIVITY CONTENT			RELEASED OF RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE					
1	6	Z	33	Z	34	35	NA	36	NA					
PERSONNEL EXPOSURES			PERSONNEL INJURIES			LOSS OF OR DAMAGE TO FACILITY			PUBLICITY					
1	7	0	0	0	37	Z	38	39	0	0	0	40	41	42
NUMBER			TYPE			DESCRIPTION			NUMBER			DESCRIPTION		
NA			NA			NA			NA			NA		
ISSUED			DESCRIPTION			NRC USE ONLY								
2	0	N	44	45	8211040270 821028 PDR ADOCK 05000416 S PDR			NRC USE ONLY						

NAME OF PREPARER Original signed by W. H. Chenault

PHONE: _____