



Carolina Power & Light Company

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429

October 22, 1982

FILE: B09-13510C
SERIAL: BSEP/82-2321

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street N.W.
Atlanta, GA 30303

82 OCT 29 A10:35

USNRC REGION II
ATLANTA, GEORGIA

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-324
LICENSE NO. DPR-62
LICENSEE EVENT REPORT 2-81-146

Dear Mr. O'Reilly:

This submittal is to correct a clerical error made when two distinct reportable events, occurring in 1981, were assigned the same LER number (2-81-73).

On August 25, 1981, a reportable event occurred involving a failure of the Unit No. 2 RCIC System, which was reported on September 11, 1981, as LER 2-81-73 (Serial No. BSEP/81-1695). On September 20, 1981, a reportable event occurred involving a failure encountered with the starting air system of No. 4 diesel generator, which was also reported as LER 2-81-73 (Serial No. BSEP/81-1948). This submittal hereby assigns LER 2-81-146 to the report of the No. 4 diesel generator problem and includes a corrected NRC Form 366.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

RMP/jo

Enclosures

cc: Mr. R. C. DeYoung

OFFICIAL COPY

8211040287 821022
PDR ADOCK 05000324
S PDR

IE 22