

DMB



Northern States Power Company

414 Nicollet Mall  
Minneapolis, Minnesota 55401  
Telephone (612) 330-5500

October 25, 1982

Regional Administrator  
Region III  
U S Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

MONTICELLO NUCLEAR GENERATING PLANT  
Docket No. 50-263 License No. DPR-22

Cracks in Recirculation System - Update Report

An Updated Licensee Event Report for LER 82-016 is attached. A final report will be submitted in response to IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation System Piping at BWR Plants".

*David Musolf*

David Musolf  
Manager - Nuclear Support Services

DMM/bd

cc: NRC Document Control Desk (1)  
NRC Resident Inspector  
MPCA  
Attn: J W Ferman

8211040378 821025  
PDR ADOCK 05000263  
S PDR

*IE 22*  
OCT 29 1982