

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	1	0	0	0	3	2	8	7	0	9	3	0	8	2	8	1	0	2	9	8	2	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DUCKET NUMBER EVENT DATE REPORT DATE

0 2 | Unit 2 in mode 1 at 96% RTP. At 0005 (C) on 09/30/82, the lower containment

0 3 | personnel airlock outer door was discovered broken. This event required entry into

0 4 | LCO 3.6.1.3. There was no effect on public health or safety. Previous

0 5 | occurrences - two (SQRO-50-328/82049 and 82060).

0 6 |

0 7 |

0 8 |

7 8 9

SYSTEM CODE 0 9		CAUSE CODE S A		CAUSE SUBCODE E		COMPONENT CODE P E N E T R						COMP. SUBCODE A		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
17 LER/RO REPORT NUMBER		EVENT YEAR 8 2		SEQUENTIAL REPORT NO. 1 2 0		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0					
23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38
ACTION TAKEN A		FUTURE ACTION X		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER N	
39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54
ACTION TAKEN A		FUTURE ACTION X		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER N	
55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70
ACTION TAKEN A		FUTURE ACTION X		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER N	

1 0 The inner door was immediately secured closed. Investigation revealed a failed  
1 1 cam-roller bearing in the door gear box. The most probable cause of the failed  
1 2 bearing has been contributed to normal wear and poor preventive maintenance during  
1 3 plant construction. The bearing was replaced and the door returned to service at  
1 4 0610 (C) on 09/30/82. Plans are being initiated to overhaul the doors at an outage  
of sufficient duration.

FACILITY STATUS				% POWER				OTHER STATUS				METHOD OF DISCOVERY				DISCOVERY DESCRIPTION					
1	5	E	28	0	9	6	29	NA				B	31	Personnel observation							
ACTIVITY CONTENT				RELEASED OF RELEASE				AMOUNT OF ACTIVITY				LOCATION OF RELEASE									
1	6	Z	33	Z	34	NA				NA											
PERSONNEL EXPOSURES				PERSONNEL INJURIES				LOSS OF OR DAMAGE TO FACILITY				PUBLICITY									
NUMBER				NUMBER				TYPE				DESCRIPTION									
1	7	0	0	0	37	Z	38	NA				0	0	0	40	Z	42	NA			
ISSUED				DESCRIPTION				8211080244 821029 PDR ADOCK 05000328 S PDR				NRC USE ONLY									
7	0	N	44	NA																	

Phone: (615) 751-0349