

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	2	1	7	0	9	2	5	7	9	8	1	1	0	2	8	2	9
60	61									68	69						74	75						80
DOCKET NUMBER											EVENT DATE						REPORT DATE							

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 With Unit 1 in run mode, secondary containment was momentarily violated
03 (T.S.3.7.c.1) when both doors of the refueling floor ventilation room
04 air lock were opened. Personnel working inside the room had to use the
05 interlock over-ride to exit the room since the outside door was open or
06 ajar. Immediately following the incident, secondary containment was
07 proven by procedure HNP-1-3653 to comply with T.S.3.7.c.2. Public health
08 and safety were not affected by this repetitive event(Ref:LER 1-79-068).

0 9		SYSTEM CODE S A		CAUSE CODE B		CAUSE SUBCODE A		COMPONENT CODE P E N E T R						COMP. SUBCODE A		VALVE SUBCODE Z																								
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47
LER/RO REPORT NUMBER		EVENT YEAR 7 9		SEQUENTIAL REPORT NO. 0 7 4		OCCURRENCE CODE 0 3		REPORT TYPE X		REVISION NO. 1		ACTION TAKEN F		FUTURE ACTION Z		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER A		COMPONENT MANUFACTURER X 9 9 9												

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this event was that the outside airlock door was not secure
1 1 ly latched or was left open. Investigation could not determine how the
1 2 door became open. All secondary containment airlock doors were
1 3 modified (by 10/80), with new locking hardware and with an interlocking
1 4 logic circuitry to prevent further recurrence.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	E	28	0	9	9	29	NA	30
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	Z	33	Z	34	NA	35	NA	36
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION			
1	7	0	0	0	37	Z	38	NA	39
PERSONNEL INJURIES		NUMBER		DESCRIPTION					
1	8	0	0	0	40	NA	41		
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
1	9	Z	42	NA	43	8211150439 821102 PDR ADOCK 05000321 S PDR			
PUBLICITY		ISSUED		DESCRIPTION					
2	0	N	44	NA	45				

NAME OF PREPARER S. B. Tipps

PHONE: (912) 367-7851