



Carolina Power & Light Company

Brunswick Steam Electric Plant  
P. O. Box 10429  
Southport, NC 28461-0429

November 4, 1982

FILE: B09-13510C  
SERIAL: BSEP/82-2440

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II, Suite 3100  
101 Marietta Street N.W.  
Atlanta, GA 30303

NOV 9 A10:30

REGION II  
ATLANTA, GEORGIA

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NO. 1  
DOCKET NO. 50-325  
LICENSE NO. DPR-71

CONFIRMATION FACSIMILE OF AN IMMEDIATELY REPORTABLE EVENT (1-82-127)

Dear Mr. O'Reilly:

This confirms the telephone conversation at 0915 on November 4, 1982, between Mr. R. M. Poulk, Jr. and Mr. C. W. Hehl concerning an immediately reportable event per Technical Specification 6.9.1.8c.

At 1159 on November 3, 1982, it was determined that the required diesel generator quick starts for diesel generators 2, 3, and 4 were not performed within 12 hours as required by Technical Specification 3.8.1.1. The quick starts were immediately performed on all three diesels satisfactorily. Diesel generator No. 1 was taken out of service at 0920 on November 2, 1982, to perform periodic testing. Quick starts were performed on diesel generators 2, 3, and 4 at 0955 on November 2, 1982 and again at 2122 on November 2, 1982. Due to a personnel error, the next scheduled performance for the quick starts at 0920 on November 3 was not performed. An investigation of this event is in progress and the results will be reported in the 14-day report.

Very truly yours,

C. R. Dietz, General Manager  
Brunswick Steam Electric Plant

RMP/dj/LETDJ3

Enclosure

cc: Mr. R. C. DeYoung

OFFICIAL COPY  
IE 22

8211150580 821104  
PDR ADOCK 05000325  
S PDR