

3150-0011
EXPIRES 4-30-82

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | 49 | 50 | 51 | 52 | 53 | 54 | 55 | 56 | 57 | 58 | 59 | 60 | 61 | 62 | 63 | 64 | 65 | 66 | 67 | 68 | 69 | 70 | 71 | 72 | 73 | 74 | 75 | 76 | 77 | 78 | 79 | 80 | 81 | 82 | 83 | 84 | 85 | 86 | 87 | 88 | 89 | 90 | 91 | 92 | 93 | 94 | 95 | 96 | 97 | 98 | 99 |

CON'T

01 REPORT SOURCE 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
7 8 DOCKET NUMBER EVENT DATE REPORT DATE
L (6) 0 5 0 0 0 3 9 5 (7) 1 0 1 4 8 2 (8) 1 1 1 1 8 2 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On October 14, 1982, with the Plant in Mode 3, the "B" Train Control Room

0 3 | Ventilation System was declared inoperable for maintenance. A pressure

0 4 | regulator for the damper (XVB0004B) actuator failed. There was no adverse

0 5 | consequence as a redundant train of ventilation remained OPERABLE and was

0 6 | placed in service.

0 7 |

0 8 |

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE					
0	9	A	A	E	X	V	A	L	V	E	X	X	H				
7	8	9	10	11	12	13	14	15	16	17	18	19	20				
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
8	2	8	2	0	2	3	0	3	L	0							
21	22	23	24	25	26	27	28	29	30	31	32						
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
A	Z	Z	Z	Z	Z	0	0	0	0	Y	N	A	X	0	0	2	
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	An air pressure regulator diaphragm ruptured. The diaphragm was replaced with
1	1	a new one. The system was declared OPERABLE per applicable Surveillance Test
1	2	Procedure.
1	3	
1	4	

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (1) 5 (B) (28) % POWER (0) (0) (0) (29) OTHER STATUS (30) N/A METHOD OF DISCOVERY (A) (31) DISCOVERY DESCRIPTION (32) Incidental Observation

ACTIVITY CONTENT RELEASED OF RELEASE (35) LOCATION OF RELEASE (36)

1 6 33 34 N/A N/A

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
1	7	000	(37) Z (38)	N/A

PERSONNEL INJURIES
NUMBER DESCRIPTION

1 8 0 0 0 40 N/A

LOSS OF OR DAMAGE TO FACILITY					
TYPE		DESCRIPTION			
1	9	Z	(42)		N/A

[illegible]

RC USE ONLY

NAME OF PREPARER

PHONE: (803) 345-5209