



Commonwealth Edison  
Braidwood Nuclear Power Station  
Route #1, Box 84  
Braceville, Illinois 60407  
Telephone 815/458-2801

May 9, 1994  
BW/94-0084

Mr. John B. Martin  
Regional Administrator  
U.S. Nuclear Regulatory Commission  
Region III  
801 Warrenville Road  
Lisle, Illinois 60532-4351

- References: (1) Confirmatory Action Letter RIII-94-005  
for Braidwood Unit 2
- (2) Braidwood letter BW/94-0075, K. L. Kofron  
to Mr. J. B. Martin, May 6, 1994

Dear Mr. Martin:

Subject: Additional information on completion of actions  
contained in Confirmatory Action Letter (CAL)  
RIII-94-005 for Braidwood Unit 2

Reference 1 required that Braidwood Station inform the NRC, in writing, when the actions contained in the CAL were complete. Reference 2 contained Commonwealth Edison's response to Reference 1 and stated that all thermocouple funnels on Braidwood Unit 2 had been inspected, and their pins were found to be installed correctly. A more detailed review of the inspection data and additional visual inspections showed that another thermocouple funnel was also missing a pin. The missing pin was located on top of the upper internals and retrieved.

Commonwealth Edison will be conducting corrective/preventive repairs on the Unit 2 thermocouple funnels.

This information was communicated to Mr. Edward G. Greenman of your staff by Mr. Karl Kaup, Braidwood Station Site Vice President, in a telephone conversation at 0805 on May 9, 1994. Mr. David J. Miller, Braidwood Station Technical Services Superintendent, informed Mr. Rolf A. Westberg, Augmented Inspection Team Leader, via telephone on Saturday, May 7, 1994, and updated this information at approximately 1000 on May 9, 1994.

9405130108 940509  
PDR ADDCK 05000457  
P PDR

JE34 1/0

MAY 9 1994


Mr. John B. Martin

2

May 9, 1994

If you have any questions, contact Mr. David J. Miller at Braidwood Station, (815) 458-2801, extension 2114.

Sincerely,



K. L. Kofron  
Station Manager  
Braidwood Station

KLK/DH/dla

cc: K. G. Bartes, Regulatory Assurance Supervisor  
D. J. Miller, Technical Services Superintendent  
D. Cooper, Operations Manager  
A. Checca, Systems Engineering Supervisor